

# **Final Product Change Notification**

Issue Date:17-Mar-2018Effective Date:25-Jun-2018

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online

## 201801009F01



#### **Management Summary**

Cu Wire is being added as a wirebond material option for LPC18xx, LPC18x0, LPC43xx and LPC43x0 in BGA packages at assembly site NXP-ATKH.

### Change Category

| [] Wafer Fab Process   | [] Assembly<br>Process | [] Product Marking             | [] Test<br>Location | [] Design     |
|------------------------|------------------------|--------------------------------|---------------------|---------------|
| [] Wafer Fab Materials | [X]<br>Assembly        | [] Mechanical<br>Specification | []Test<br>Process   | [] Errata     |
| ] Wafer Fab Location   | Materials              |                                | []Test              | [] Electrical |
|                        | Location               | Packing/Shipping/Labeling      |                     |               |
| LPC18xx, LPC43xx BGA   |                        |                                |                     |               |

LPC18xx, LPC43xx BGA Package Cu Wire Qualification for NXP-ATKH

#### **Details of this Change**

Copper wire has been qualified and will be added as a wirebond material. To support a robust wirebond process the mold compound has also changed. Upon effective date, NXP will begin shipping product with copper wire.

See attached Self Qualification Reports (SQR) for details of the affected part numbers, material changes and qualification test results.

Samples of the following superset part numbers will be available. LPC1830FET100, LPC1850FET180, LPC1850FET256, LPC4350FET180, LPC4350FET256, LPC4370FET100, LPC1857FET256, LPC1857JBD208, LPC1857JET256 LPC4367JBD208, LPC4367JET100, LPC4367JET256 Why do we Implement this Change Adding Copper wire is required to mitigate against raw material cost increases and for supply assurance. The die attach material, and mold compound change enable a robust Cu wirebond process.

#### Identification of Affected Products

Top side marking

Product version is incremented. See marking details in attached Self Qualification Report (SQR) document.

## Product Availability

Sample Information

Samples are available from 30-Mar-2018

Sample requests can be sent to the email address below in Contact and Support.

**Production** Planned first shipment 25-Jun-2018

#### Impact

Wire composition and mold compound are the only changes. No Impact to form, fit or function. Reliability is equivalent or improved.

Data Sheet Revision

No impact to existing datasheet **Disposition of Old Products** 

Existing inventory will be shipped until depleted

**Timing and Logistics** 

Your acknowledgement of this change, conform JEDEC JESD46 D, is expected till 16-Apr-2018.

**Contact and Support** 

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

 Name
 Tim Camenzind

 Position
 Senior Quality Engineer

 e-mail address
 tim.camenzind@nxp.com

 At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

 Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

| View Notification | Subscription | Support |
|-------------------|--------------|---------|
|-------------------|--------------|---------|

#### **Affected Part Numbers**

LPC1850FET256,551 LPC18S37JET100E LPC1833FET256,551 LPC1837FET256,551 LPC1857FET256,551 LPC4330FET256,551 LPC4350FET256,551 LPC4330FET180,551 LPC4357FET256,551 LPC4337FET256,551 LPC4333FET256,551 LPC4357JET256,551 LPC4337JET256,551 LPC4333JET256,551 LPC4370FET256E LPC4370FET100E LPC4333JET100E LPC4337JET100E LPC1812JET100E LPC1833JET100E LPC1837JET100E LPC4367JET256E LPC18S30FET256E LPC43S37JET100E LPC43S57JET256E