

Product Bulletin

Document #: PB24393X1 Issue Date: 07 Oct 2022

Title of Change:	Update for PB24393X - To identify specific sites affected with the change including the transition period.				
Effective date:	07 Oct 2022				
Contact information:	Contact your local onsemi Sales Office or KrisJudelo.Dayna@onsemi.com				
Type of notification:	This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin.				
Change Category:	Test Change				
Change Sub-Category(s):	Shipping/Packaging/Marking				
Sites Affected:					
onsemi Sites		External Foundry/Subcon Sites			
onsemi Cebu, Philippines		Greatek Electronics Inc., Taiwan			
onsemi Leshan, China		HANA Microelectronics, China			
onsemi Seremban, Malaysia		JCET, China			

Description and Purpose:


This update to PB24393X is to list all of the affected sites and clarify that the transition period will be until Dec 31,2022.

SOSM and SOT223 package assembled in various listed sites will start to use onsemi Marking Layout Configuration

This is part of the alignment and marking standardization.

For a specific OPN that is build in different sites will now have the same lay out scheme and will just differ on the plant code.

Sample marking change below.



Legend:

X = Device Mark M = Month Code A = Plant Code Y = Year Code

W = Week Code

Note: This information is generic. Please refer to device data sheet for actual part marking. Pin1 indicator, Pb–Free indicator, microdot, may or may not be present.

Some products may not follow the Generic

Some products may not follow the Generic Marking.

TEM001796 Rev. D Page 1 of 2



Product Bulletin

Document #: PB24393X1 Issue Date: 07 Oct 2022

List of Affected Standard Parts:

Note: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the **PCN Customized Portal**.

FDC8602	FDG1024NZ	FDG6306P	
FDG6332C	FDG6332C-F085	FDG6332C-PG	
FDG6335N	FDG8842CZ	FDG8850NZ	
FDN028N20	FDN302P	FDN304P	
FDN304PZ	FDN306P	FDN308P	
FDN327N	FDN335N	FDN336P	
FDN337N	FDN338P	FDN339AN	
FDN340P	FDN342P	FDN352AP	
FDN357N	FDN358P	FDN359AN	
FDN359BN	FDN360P	FDN361BN	
FDN537N	FDT86246	FDT86244	
FDT86113LZ	FDT86106LZ	FDT86102LZ	
FDT458P	FDT457N	FDT439N	
FDT3612	FDT1600N10ALZ	FDN86501LZ	
FDN86265P	FDN86246	FDN8601	
FDN5632N-F085	FDN5630	FDN5618P	

TEM001796 Rev. D Page 2 of 2



Appendix A: Changed Products

PCN#: PB24393X1 Issue Date: Oct 07, 2022

DIKG: DIGI-KEY

Product	Customer Part Number	Qualification Vehicle	New Part Number	Replacement Supplier		
FDC8602						
FDG6306P						
FDG6332C						
FDG6332C-F085						
FDG6335N						
FDG8842CZ						
FDG8850NZ						
FDN028N20						
FDN302P						
FDN304P						
FDN304PZ						
FDN306P						
FDN308P						
FDN327N						
FDN335N						
FDN336P						
FDN337N						
FDN338P						
FDN339AN						
FDN340P						
FDN342P						
FDN352AP						
FDN357N						
FDG1024NZ						
FDN359AN						
FDN358P						
FDN360P						
FDN359BN						
FDN537N						
FDN361BN						
FDT86244						
FDT86246						
FDT86106LZ						
FDT86113LZ						
FDT458P						
FDT86102LZ						
FDT439N						
FDT457N						
FDT1600N10ALZ						
FDT3612						
FDN86265P						
FDN86501LZ						
FDN86246						
FDN5632N-F085						
FDN8601						
FDN5630						
FDN5618P						
רטואסואר	l	l	l	l .		