



Description of Notification

- Starting the week of July 7th, customers purchasing from the attached list of KK® 396 family headers may see spots on the header pins
- The spots have been tested by Molex Quality and have been confirmed to be cosmetic in nature. The spots WILL NOT affect form, fit or function of the headers







Examples of discoloration spots, enlarged




KK® 396 Header series affected

- **)**41791
- **)** 41792
- >41661
- **)** 41662
- **)**41671
- **)**41672
- **)** 41681
- **)**171813
- 171814









Deviation Justification

- Molex's internal deviation was created to use headers as is, to prevent shipment interruptions: deviation per section 6.7 of Molex Cosmetic Specification document number PS-45499-002 (attached)
- Molex quality engineers have determined the parts with the spots are functional to Molex's product specifications
- Please do not enter quality notifications in relation to this issue
- Additional quality/testing data is available upon request
- If you or your customers have any questions, please contact your Molex sales representative.

