



Product Change Notification

TE Connectivity

Product Change Notification: PCN-23-194041

PCN Date: 05-DEC-23

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Change from single-plant manufacturing location to flexible dual-factory manufacturing.

Description of Changes

Manufacturing location change. The following part numbers will be transferred from TE's HMO facility in Hermosillo Mexico to a dual-location configuration with manufacturing in either TE's HMO or TE's Penang Malaysia facility. Decisions on manufacturing site will be determined by TE to provide best overall customer experience. For qualification, our processes follow a strict transfer procedure, which ensures no negative influence on quality, ability to supply, and form-fit-function of the concerned products. Note that TE's Penang Malaysia site currently makes products within these same families; so minimal new tools or processes are required. The Penang site is under a certified quality management system according to standard industry requirements. To guarantee performance, an internal release process based on specifications will be executed before any parts will be delivered.

Reason for Changes:

Transfer of Manufacturing location for overall improvement of on-time delivery and lead-time. This serves a 30 day notice of a manufacturing location change. IF TE does not hear from you within this notice period, TE will consider this as acceptance of the PCN change communicated.

PCN Attributes:

Product Category:

Antennas

Kind of Change:

Location Change

Change Feature:

No Feature Change

Potential Customer Impact:

Additional Location

Remarks:

Change from single-plant manufacturing location to flexible dual-factory manufacturing.

| | |
|---|---|
| Estimated Dates: | |
| Last Order Date (Obsolete Parts Only): | First Ship Date of Changed Items (Changed Parts Only): |
| | 08-JAN-2024 |
| Last Ship Date of Changed Items (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): |
| | No Mixed Shipments |
| Effectivity Date: | Date of First Samples: |
| | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| EXC450BN | NO | | | | | | |
| EXC450TN | NO | | | | | | |
| EXC902BN | NO | | | | | | |
| EXC902SM | NO | | | | | | |
| EXD450SMV | NO | | | | | | |
| EXD470MX | NO | | | | | | |
| EXR420BN | NO | | | | | | |
| EXR450BN | NO | | | | | | |
| EXR450TN | NO | | | | | | |
| G420BN | NO | | | | | | |
| G450BN | NO | | | | | | |
| G8BI | NO | | | | | | |
| G8MI | NO | | | | | | |
| G8PI | NO | | | | | | |
| G8U | NO | | | | | | |
| G8UM | NO | | | | | | |
| G8UT | NO | | | | | | |
| G8XTI | NO | | | | | | |
| GB8 | NO | | | | | | |
| GB8TI15 | NO | | | | | | |
| GB8UM-L | NO | | | | | | |
| GBR8 | NO | | | | | | |
| GBR8PI | NO | | | | | | |
| GMB195SMI | NO | | | | | | |
| GR8 | NO | | | | | | |
| GR8PI | NO | | | | | | |
| LBBMB8U | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| LBM9038 | NO | | | | | | |
| LBMB8 | NO | | | | | | |
| LBMB9034-L | NO | | | | | | |
| LBT8U | NO | | | | | | |
| LBTB3400 | NO | | | | | | |
| MABT8 | NO | | | | | | |
| MABT8U | NO | | | | | | |
| MABVT8U | NO | | | | | | |
| MB195SMI14 | NO | | | | | | |
| MB820 | NO | | | | | | |
| MB8L | NO | | | | | | |
| MB8MI | NO | | | | | | |
| MB8U | NO | | | | | | |
| MB8U-BP-25 | NO | | | | | | |
| MB8UM | NO | | | | | | |
| MB8UMI | NO | | | | | | |
| MB8UP | NO | | | | | | |
| MB8UP22 | NO | | | | | | |
| MB8X | NO | | | | | | |
| MBD | NO | | | | | | |
| MBF | NO | | | | | | |
| NMOHPCFSMAM518 | NO | | | | | | |
| NMOHPCNSMAM518 | NO | | | | | | |
| TM8 | NO | | | | | | |
| TMB8U | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-----------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| GB8 | NO | | | | | | |
| MB8UP | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| EXC450BN | NO | | | | | | |
| EXC450TN | NO | | | | | | |
| EXC902BN | NO | | | | | | |
| EXC902SM | NO | | | | | | |
| EXR450BN | NO | | | | | | |
| EXR450TN | NO | | | | | | |
| G420BN | NO | | | | | | |
| G450BN | NO | | | | | | |
| G8BI | NO | | | | | | |
| G8MI | NO | | | | | | |
| G8PI | NO | | | | | | |
| G8UM | NO | | | | | | |
| G8UT | NO | | | | | | |
| G8XTI | NO | | | | | | |
| GB8 | NO | | | | | | |
| GB8TI15 | NO | | | | | | |
| GB8UM-L | NO | | | | | | |
| GBR8PI | NO | | | | | | |
| GMB195SMI | NO | | | | | | |
| GR8 | NO | | | | | | |
| GR8PI | NO | | | | | | |
| LBBMB8U | NO | | | | | | |
| LBM9038 | NO | | | | | | |
| LBMB8 | NO | | | | | | |
| LBMB9034-L | NO | | | | | | |
| LBT8U | NO | | | | | | |
| LBTB3400 | NO | | | | | | |
| MABT8 | NO | | | | | | |
| MABT8U | NO | | | | | | |
| MABVT8U | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| MB195SMI14 | NO | | | | | | |
| MB820 | NO | | | | | | |
| MB8L | NO | | | | | | |
| MB8MI | NO | | | | | | |
| MB8U | NO | | | | | | |
| MB8U-BP-25 | NO | | | | | | |
| MB8UM | NO | | | | | | |
| MB8UMI | NO | | | | | | |
| MB8UP | NO | | | | | | |
| MB8UP22 | NO | | | | | | |
| MBD | NO | | | | | | |
| MBF | NO | | | | | | |
| NMOHPCFSMAM518 | NO | | | | | | |
| NMOHPCNSMAM518 | NO | | | | | | |
| TM8 | NO | | | | | | |
| TMB8U | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|---------------------------|---------------------------|------------------|----------------------|----------------------|------------------------|---------------------------------|---------------------------|
| EXC450BN | NO | | | | | | |
| EXC450TN | NO | | | | | | |
| EXC902BN | NO | | | | | | |
| EXC902SM | NO | | | | | | |
| EXD450SMV | NO | | | | | | |
| EXD470MX | NO | | | | | | |
| EXR420BN | NO | | | | | | |
| EXR450BN | NO | | | | | | |
| EXR450TN | NO | | | | | | |
| G420BN | NO | | | | | | |
| G450BN | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| G8BI | NO | | | | | | |
| G8MI | NO | | | | | | |
| G8PI | NO | | | | | | |
| G8U | NO | | | | | | |
| G8UM | NO | | | | | | |
| G8UT | NO | | | | | | |
| G8XTI | NO | | | | | | |
| GB8 | NO | | | | | | |
| GB8TI15 | NO | | | | | | |
| GB8UM-L | NO | | | | | | |
| GBR8 | NO | | | | | | |
| GBR8PI | NO | | | | | | |
| GMB195SMI | NO | | | | | | |
| GR8 | NO | | | | | | |
| GR8PI | NO | | | | | | |
| LBBMB8U | NO | | | | | | |
| LBM9038 | NO | | | | | | |
| LBMB8 | NO | | | | | | |
| LBMB9034-L | NO | | | | | | |
| LBT8U | NO | | | | | | |
| LBTB3400 | NO | | | | | | |
| MABT8 | NO | | | | | | |
| MABT8U | NO | | | | | | |
| MABVT8U | NO | | | | | | |
| MB195SMI14 | NO | | | | | | |
| MB820 | NO | | | | | | |
| MB8L | NO | | | | | | |
| MB8MI | NO | | | | | | |
| MB8U | NO | | | | | | |
| MB8U-BP-25 | NO | | | | | | |
| MB8UM | NO | | | | | | |
| MB8UMI | NO | | | | | | |
| MB8UP | NO | | | | | | |
| MB8UP22 | NO | | | | | | |
| MB8X | NO | | | | | | |
| MBD | NO | | | | | | |

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|--------------------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| MBE | NO | | | | | | |
| NMOHPCFSMAM518 | NO | | | | | | |
| NMOHPCNSMAM518 | NO | | | | | | |
| TM8 | NO | | | | | | |
| TMB8U | NO | | | | | | |