

Doc. No. : PDN220401
Date : Apr 14, 2022

To : Dear Valued Customers

Product Discontinuance Notice

Subject : Products discontinue.	
Parts Affected : Please refer the attached.	
Reason for Discontinuance : Follow the international halogen-free specification, meet the EU Halogen Free and RoHS requirements. Meanwhile, some parts were discontinued due to low demand.	
Alternative Products : Please refer the attached.	
Last time buy : Jun 30, 2022 Effective Date : Sep 30, 2022	
R&D Dept. Signature : 	QA Dept. Signature : 

Product Discontinuance Notice

Doc. No. : PDN220401

EOL p/n	Package	Alternative p/n
SB320-G Thru. SB3100-G	DO-201AD	SR320-HF Thru. SR3200-HF
SB520-G Thru. SB5100-G	DO-201AD	SR520-HF Thru. SR5200-HF
SR520-G Thru. SR5200-G	DO-27	SR520-HF Thru. SR5200-HF
CDBHM120L-G Thru. CDBHM180L-G	MBS	CDBHM120L-HF Thru. CDBHM180L-HF
2N7002KA-HF	SOT-23	2N7002K-HF
CDSZ01100-HF	0201/DFN0603	CDSZC01100-HF
CDSUR101A-HF	0603/SOD-523F	CDSU101A-HF
CDSUR400-HF	0603/SOD-523F	CDSU400-HF
CDSUR400B-HF	0603/SOD-523F	CDSU400B-HF
SR2150-G	DO-15	Please contact sales person or manufacturer's representative.
SR320-HF	DO-27	
SR520-HF	DO-27	
SB120-G Thru. SB1100-G	DO-41	
CDBA140LR-HF Thru. CDBA160LR-HF	DO-214AC(SMA)	
CDBA1150LR-HF Thru. CDBA1200LR-HF	DO-214AC(SMA)	
CDBA240LR-HF Thru. CDBA2200LR-HF	DO-214AC(SMA)	
CDBA340LR-HF	DO-214AC(SMA)	
CDBA3100LR-HF Thru. CDBA3200LR-HF	DO-214AC(SMA)	
CDBB240LR-HF Thru. CDBB2200LR-HF	DO-214AA(SMB)	
CDBB340LR-HF Thru. CDBB3200LR-HF	DO-214AA(SMB)	
CDBC220LR-HF Thru. CDBC2200LR-HF	DO-214AB(SMC)	
CDBC320LR-HF Thru. CDBC3200LR-HF	DO-214AB(SMC)	
CDSV914-G	SOD-323	
CDSV21H-G	SOD-323	
CDSH6-4448-G	SOT-563	
CDBV3-0720-G	SOT-323	
CDBW01540RF-HF	SOD-123	
CDBW01560RF-HF	SOD-123	