

Not Recommended for New Designs: ERJMS4 Series Resistors

Product Group #: PG24

DATE: 06.18.2025

About This Notice:	<p>To our valued customers:</p> <p>The following Panasonic Industry part numbers are being marked as Not Recommended for New Designs (NRFND). We understand that this may cause some inconvenience, however, if we have recommended alternatives, please reference the attached documents or contact us directly. We appreciate your business and look forward to continuing to serve your needs.</p>
Features:	<p>After thorough consideration and evaluation, we regret to inform you that we will no longer be recommending the use of ERJMS4 series of the metal plate resistor for new designs.</p>
Effective Date:	<p>Immediate</p>
Affected Part(s) and/or Replacement(s):	<p>See attached Affected Parts List or contact Panasonic for more information.</p>
Datasheet(s):	<p>See attached Datasheet(s). ERJMS-MB type</p>
Notes:	

Affected Part Numbers

ERJ-MS4HF10MU
ERJ-MS4HF5M0U
ERJ-MS4HF6M0U
ERJ-MS4HF7M0U
ERJ-MS4HF8M0U
ERJ-MS4HF9M0U
ERJ-MS4SF1M0U
ERJ-MS4SF2M0U
ERJ-MS4SF3M0U
ERJ-MS4SF4M0U