

Product Obsolescence Notification

Issue Date: 7-July-2025

Dear Customer:

Broadcom regrets to announce the obsolescence of the following products:

Broadcom Part Numbers	Description	Suggested Replacement
HLMP-AG74-12000	Lamp,5mm,AlInGaP,Red,30X70deg	HLMP-AG82-120D1
HLMP-AG74-120DD	Lamp,5mm,AlInGaP,Red,30X70deg	HLMP-AG82-120D1
HLMP-AG75-120DD	Lamp,5mm,AlInGaP,Red,30X70deg	HLMP-AG83-120DW
HLMP-HG74-XY000	Lamp,5mm,AlInGaP,Red,40X100deg	HLMP-HG82-XZ0D1
HLMP-HG74-XY0DD	Lamp,5mm,AlInGaP,Red,40X100deg	HLMP-HG82-XZ0D1
HLMP-HG74-XY0ZZ	Lamp,5mm,AlInGaP,Red,40X100deg	HLMP-HG82-XZ0D1
HLMP-HG75-XY0DD	Lamp,5mm,AlInGaP,Red,40X100deg	HLMP-HG83-XZ0DW
HLMP-LG73-XZ0ZZ	Lamp,4mm,AlInGaP,Red,40X100deg	HLMP-LG71-XZ0DD
HLMP-LG75-XY0DD	Lamp,4mm,AlInGaP,Red,40X100deg	HLMP-LG71-XZ0DD
HLMZ-AG74-120DD	LampZ,5mm,AlInGaP,Red,30X70deg	HLMP-AG82-120D1
HLMZ-HG74-XY000	LampZ,5mm,AlInGaP,Red,40X100deg	HLMP-HG82-XZ0D1
HLMZ-HG74-XY0DD	LampZ,5mm,AlInGaP,Red,40X100deg	HLMP-HG82-XZ0D1
HLMZ-HG75-XY0DD	LampZ,5mm,AlInGaP,Red,40X100deg	HLMP-HG83-XZ0DW
HSMA-C400	Chip,R/angle Mt,AlInGaP,Amb	N/A
HSMC-C400	Chip,R/angle Mt,AlInGaP,Red	N/A
HSME-C400	Chip,R/angle Mt,AlInGaP,Grn	N/A
HSML-C400	Chip,R/angle Mt,AlInGaP,Org	N/A
HSMQ-C400	Chip,R/angle Mt,InGan,Grn	N/A
QCMS-2930	5X7 SmartDisp 16Char .15in,Grn	HCMS-2923-GH000
QL2Z-HG74-XY0ZZ	LampZ,5mm,AlInGaP,Red,40X100deg	HLMP-HG82-XZ0D1
QLMZ-AG74-120DD	LampZ,5mm,AlInGaP,Red,30X70deg	HLMP-AG82-120D1
QLMZ-AG75-120DD	LampZ,5mm,AlInGaP,Red,30X70deg	HLMP-AG83-120DW
QLMZ-HG74-XY000	LampZ,5mm,AlInGaP,Red,40X100deg	HLMP-HG82-XZ0D1
QLMZ-HG74-XY0ZZ	LampZ,5mm,AlInGaP,Red,40X100deg	HLMP-HG82-XZ0D1
QLMZ-HG75-XY0DD	LampZ,5mm,AlInGaP,Red,40X100deg	HLMP-HG83-XZ0DW
QLMZ-LG3V-WX0DD	LampZ,4mm,AlInGaP,Red,40X100deg	HLMP-LG71-XZ0DD
QLMZ-LG3V-XY0DD	LampZ,SMT Oval,AlInGaP,Red,40X100deg	HLMP-LG71-XZ0DD
QSML-C19P	Chip,Top Mt,AlInGaP,Org	HSML-C197

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Suggested Replacement
HLMP-PB00-PR000	Poly,Ftop,InGaN,Blue	9-Aug-25	9-Feb-26	N/A
HR5P-N4AA-00000	IR Lamp,5mm, 940nm,6deg	9-Aug-25	9-Feb-26	HR5P-N4AB-00000
HR5P-N4FA-00000	IR Lamp,5mm, 940nm,50deg	9-Aug-25	9-Feb-26	HR5P-N4FB-00000

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Suggested Replacement
ASMT-CA00	Chip,R/angle Mt,0.4mm,AlInGaP,Amb	9-Oct-25	9-Apr-26	HSMA-C120
ASMT-CB00	Chip,R/angle Mt,0.4mm,InGaN,Blue	9-Oct-25	9-Apr-26	HSMR-C120
ASMT-CR00	Chip,R-angle Mt,0.4mm,AlInGaP,Red	9-Oct-25	9-Apr-26	HSMC-C120
ASMT-CW00	Chip,R/angle Mt,0.4mm,InGaN,White	9-Oct-25	9-Apr-26	HSMW-C120
HR5P-N1AA-00000	IR Lamp,5mm, 850nm,6deg	9-Oct-25	9-Apr-26	HR5P-N1AB-00000
HR5P-N1CA-00000	IR Lamp,5mm, 850nm,30deg	9-Oct-25	9-Apr-26	HR5P-N1CB-00000
HR5P-N1FA-00000	IR Lamp,5mm, 850nm,50deg	9-Oct-25	9-Apr-26	HR5P-N1FB-00000
HSMA-C177	Chip,Top Mt,AlInGaP,Amb	9-Oct-25	9-Apr-26	HSMA-C170
HSMC-C177	Chip,Top Mt, AlInGaP,Red	9-Oct-25	9-Apr-26	HSMC-C170
HSMG-C177	Chip,Top Mt,GaP,Grn	9-Oct-25	9-Apr-26	HSMG-C170
HSMQ-C177	Chip,Top Mt,InGaN,Grn	9-Oct-25	9-Apr-26	HSMQ-C170
HSMS-C177	Chip,Top Mt,HER	9-Oct-25	9-Apr-26	HSMS-C170
HSMY-C177	Chip,Top Mt,GaP,Yel	9-Oct-25	9-Apr-26	HSMY-C170
QSMT-CB10	Chip,R/angle Mt,0.4mm,InGaN,Blue	9-Oct-25	9-Apr-26	HSMR-C120
QSMT-CG02	Chip,R-angle Mt,0.4mm,InGaN,Grn	9-Oct-25	9-Apr-26	HSMQ-C120
QSMT-CR02	Chip,R-angle Mt,0.4mm,AlInGaP,Red	9-Oct-25	9-Apr-26	HSMC-C120
QSMT-CW0B	Chip,R/angle Mt,0.4mm,InGaN,White	9-Oct-25	9-Apr-26	HSMW-C120

Broadcom Part Numbers	Description	LTB Date (LTB)	LTS Date (LTS)	Suggested Replacement
ASCB-GTF2-0A307	1212 Tricolor PLCC-4 LED	9-Jan-26	9-Jul-26	N/A
ASMR-LD0A-AGH0D	PLCC4,MPWR,T/Mt,0.5W, AllnGaP2,Red	9-Jan-26	9-Jul-26	ASMT-QRBD-AGH0E
AZMC-PRB9-TV005	PLCC4,PWR,T/Mt,120VA, AllnGaP2,Red	9-Jan-26	9-Jul-26	ASMT-SRB4-YX305
AZMT-SAB4-PW905	PLCC4,PN14,120VA, AllnGaP,Amb	9-Jan-26	9-Jul-26	ASMT-SAB4-YX305
AZMT-SHB4-PW905	PLCC4,PN14,120VA, AllnGaP,Rorg	9-Jan-26	9-Jul-26	ASMT-SHB4-YX305
AZMT-SRB4-PW505	PLCC4,PN14,120VA, AllnGaP,Red	9-Jan-26	9-Jul-26	ASMT-SRB4-YX305
AZMT-SRB4-PW705	PLCC4,PN14,120VA, AllnGaP,Red	9-Jan-26	9-Jul-26	ASMT-SRB4-YX305
HSMA-A160-S7WJ1	PLCC2,Top Mt,Black,AllnGaP,Amb	9-Jan-26	9-Jul-26	HSMA-A101-S70J1
HZMC-A400-T30M1	PLCC4,PWR,T/Mt,120VA, AllnGaP,Red	9-Jan-26	9-Jul-26	HSMC-A401-U80M1
QDSM-728B	0.5" 3Digit InGan Blue,CA, Black TP	9-Jan-26	9-Jul-26	N/A
QZMC-PHM1-TW005	PLCC4,PWR,T/Mt,120VA, AllnGaP2,Rorg	9-Jan-26	9-Jul-26	ASMT-SHB4-YX305

Please provide your Broadcom Sales Office with your lifetime Last Time Buy order requirements (LTB) for the above products no later than the date noted in the above table. These orders are non-cancelable, non-returnable and cannot be rescheduled. Orders received after the Last Time Buy (LTB) order date noted in the above table cannot be accepted.

The last requested delivery date for these orders may not be later than the Last Time Ship (LTS) date noted in the above table. Due to inherent variations in yields, Broadcom reserves the right to ship up to 5% under the original last time buy quantity, and this quantity will fully satisfy Broadcom's obligation to deliver that product under this last time buy agreement.

All last time buy orders must be placed based on Broadcom's minimum order quantity (MOQ) requirements per the above table. All prior commitments regarding Broadcom's minimum order requirements do not apply to last time buy orders. Broadcom reserves the right to limit last time buy quantities based on capacity and material availability.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.