



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 901-020    | Old Rev. | T | New Rev. | U |
|                | 901-030    |          | T |          | U |
|                | 901-035    |          | T |          | U |
|                | 901-040    |          | T |          | U |
|                | 901-045    |          | T |          | U |
|                | 901-050    |          | T |          | U |
|                | 901-055    |          | T |          | U |
|                | 901-060    |          | T |          | U |
|                | 901-065    |          | T |          | U |
|                | 901-070    |          | T |          | U |
|                | 901-075    |          | T |          | U |
|                | 901-080    |          | T |          | U |
|                | 901-085    |          | T |          | U |
|                | 901-090    |          | T |          | U |
|                | 901-095    |          | T |          | U |
|                | 901-1.000  |          | T |          | U |
|                | 901-1.065  |          | T |          | U |
|                | 901-1.125  |          | T |          | U |
|                | 901-1.180  |          | T |          | U |
|                | 901-1.250  |          | T |          | U |
|                | 901-100    |          | T |          | U |
|                | 901-105    |          | T |          | U |
|                | 901-10MM   |          | T |          | U |
|                | 901-110    |          | T |          | U |
|                | 901-115    |          | T |          | U |
|                | 901-11MM   |          | T |          | U |
|                | 901-120    |          | T |          | U |
|                | 901-120 GN |          | T |          | U |
|                | 901-125    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 901-12MM | Old Rev. | T | New Rev. | U |
|                | 901-130  |          | T |          | U |
|                | 901-135  |          | T |          | U |
|                | 901-13MM |          | T |          | U |
|                | 901-140  |          | T |          | U |
|                | 901-145  |          | T |          | U |
|                | 901-150  |          | T |          | U |
|                | 901-155  |          | T |          | U |
|                | 901-15MM |          | T |          | U |
|                | 901-160  |          | T |          | U |
|                | 901-165  |          | T |          | U |
|                | 901-16MM |          | T |          | U |
|                | 901-170  |          | T |          | U |
|                | 901-175  |          | T |          | U |
|                | 901-177  |          | T |          | U |
|                | 901-17MM |          | T |          | U |
|                | 901-180  |          | T |          | U |
|                | 901-185  |          | T |          | U |
|                | 901-187  |          | T |          | U |
|                | 901-18MM |          | T |          | U |
|                | 901-190  |          | T |          | U |
|                | 901-195  |          | T |          | U |
|                | 901-19MM |          | T |          | U |
|                | 901-1MM  |          | T |          | U |
|                | 901-200  |          | T |          | U |
|                | 901-205  |          | T |          | U |
|                | 901-20MM |          | T |          | U |
|                | 901-210  |          | T |          | U |
|                | 901-215  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 901-21MM   | Old Rev. | T | New Rev. | U |
|                | 901-220    |          | T |          | U |
|                | 901-225    |          | T |          | U |
|                | 901-22MM   |          | T |          | U |
|                | 901-230    |          | T |          | U |
|                | 901-235    |          | T |          | U |
|                | 901-240    |          | T |          | U |
|                | 901-245    |          | T |          | U |
|                | 901-250    |          | T |          | U |
|                | 901-255    |          | T |          | U |
|                | 901-260    |          | T |          | U |
|                | 901-265    |          | T |          | U |
|                | 901-270    |          | T |          | U |
|                | 901-270 BE |          | T |          | U |
|                | 901-275    |          | T |          | U |
|                | 901-280    |          | T |          | U |
|                | 901-285    |          | T |          | U |
|                | 901-290    |          | T |          | U |
|                | 901-295    |          | T |          | U |
|                | 901-295 BK |          | T |          | U |
|                | 901-2MM    |          | T |          | U |
|                | 901-300    |          | T |          | U |
|                | 901-305    |          | T |          | U |
|                | 901-310    |          | T |          | U |
|                | 901-315    |          | T |          | U |
|                | 901-320    |          | T |          | U |
|                | 901-325    |          | T |          | U |
|                | 901-32MM   |          | T |          | U |
|                | 901-330    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 901-335 | Old Rev. | T | New Rev. | U |
|                | 901-340 |          | T |          | U |
|                | 901-345 |          | T |          | U |
|                | 901-350 |          | T |          | U |
|                | 901-355 |          | T |          | U |
|                | 901-360 |          | T |          | U |
|                | 901-365 |          | T |          | U |
|                | 901-370 |          | T |          | U |
|                | 901-375 |          | T |          | U |
|                | 901-380 |          | T |          | U |
|                | 901-385 |          | T |          | U |
|                | 901-390 |          | T |          | U |
|                | 901-395 |          | T |          | U |
|                | 901-3MM |          | T |          | U |
|                | 901-400 |          | T |          | U |
|                | 901-405 |          | T |          | U |
|                | 901-410 |          | T |          | U |
|                | 901-415 |          | T |          | U |
|                | 901-420 |          | T |          | U |
|                | 901-425 |          | T |          | U |
|                | 901-430 |          | T |          | U |
|                | 901-435 |          | T |          | U |
|                | 901-437 |          | T |          | U |
|                | 901-440 |          | T |          | U |
|                | 901-445 |          | T |          | U |
|                | 901-450 |          | T |          | U |
|                | 901-455 |          | T |          | U |
|                | 901-460 |          | T |          | U |
|                | 901-465 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 901-470 | Old Rev. | T | New Rev. | U |
|                | 901-475 |          | T |          | U |
|                | 901-480 |          | T |          | U |
|                | 901-485 |          | T |          | U |
|                | 901-490 |          | T |          | U |
|                | 901-495 |          | T |          | U |
|                | 901-4MM |          | T |          | U |
|                | 901-500 |          | T |          | U |
|                | 901-505 |          | T |          | U |
|                | 901-510 |          | T |          | U |
|                | 901-515 |          | T |          | U |
|                | 901-520 |          | T |          | U |
|                | 901-525 |          | T |          | U |
|                | 901-530 |          | T |          | U |
|                | 901-535 |          | T |          | U |
|                | 901-540 |          | T |          | U |
|                | 901-545 |          | T |          | U |
|                | 901-550 |          | T |          | U |
|                | 901-555 |          | T |          | U |
|                | 901-560 |          | T |          | U |
|                | 901-562 |          | T |          | U |
|                | 901-565 |          | T |          | U |
|                | 901-570 |          | T |          | U |
|                | 901-575 |          | T |          | U |
|                | 901-580 |          | T |          | U |
|                | 901-585 |          | T |          | U |
|                | 901-590 |          | T |          | U |
|                | 901-595 |          | T |          | U |
|                | 901-5MM |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 901-600 | Old Rev. | T | New Rev. | U |
|                | 901-605 |          | T |          | U |
|                | 901-610 |          | T |          | U |
|                | 901-615 |          | T |          | U |
|                | 901-620 |          | T |          | U |
|                | 901-625 |          | T |          | U |
|                | 901-630 |          | T |          | U |
|                | 901-635 |          | T |          | U |
|                | 901-640 |          | T |          | U |
|                | 901-645 |          | T |          | U |
|                | 901-650 |          | T |          | U |
|                | 901-655 |          | T |          | U |
|                | 901-660 |          | T |          | U |
|                | 901-665 |          | T |          | U |
|                | 901-670 |          | T |          | U |
|                | 901-675 |          | T |          | U |
|                | 901-680 |          | T |          | U |
|                | 901-685 |          | T |          | U |
|                | 901-690 |          | T |          | U |
|                | 901-695 |          | T |          | U |
|                | 901-6MM |          | T |          | U |
|                | 901-700 |          | T |          | U |
|                | 901-705 |          | T |          | U |
|                | 901-710 |          | T |          | U |
|                | 901-715 |          | T |          | U |
|                | 901-720 |          | T |          | U |
|                | 901-725 |          | T |          | U |
|                | 901-730 |          | T |          | U |
|                | 901-735 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 901-740 | Old Rev. | T | New Rev. | U |
|                | 901-745 |          | T |          | U |
|                | 901-750 |          | T |          | U |
|                | 901-755 |          | T |          | U |
|                | 901-760 |          | T |          | U |
|                | 901-765 |          | T |          | U |
|                | 901-770 |          | T |          | U |
|                | 901-775 |          | T |          | U |
|                | 901-780 |          | T |          | U |
|                | 901-785 |          | T |          | U |
|                | 901-790 |          | T |          | U |
|                | 901-795 |          | T |          | U |
|                | 901-7MM |          | T |          | U |
|                | 901-800 |          | T |          | U |
|                | 901-805 |          | T |          | U |
|                | 901-810 |          | T |          | U |
|                | 901-815 |          | T |          | U |
|                | 901-820 |          | T |          | U |
|                | 901-825 |          | T |          | U |
|                | 901-830 |          | T |          | U |
|                | 901-835 |          | T |          | U |
|                | 901-840 |          | T |          | U |
|                | 901-845 |          | T |          | U |
|                | 901-850 |          | T |          | U |
|                | 901-855 |          | T |          | U |
|                | 901-860 |          | T |          | U |
|                | 901-865 |          | T |          | U |
|                | 901-870 |          | T |          | U |
|                | 901-875 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 901-880 | Old Rev. | T | New Rev. | U |
|                | 901-885 |          | T |          | U |
|                | 901-890 |          | T |          | U |
|                | 901-895 |          | T |          | U |
|                | 901-8MM |          | T |          | U |
|                | 901-900 |          | T |          | U |
|                | 901-905 |          | T |          | U |
|                | 901-910 |          | T |          | U |
|                | 901-915 |          | T |          | U |
|                | 901-920 |          | T |          | U |
|                | 901-925 |          | T |          | U |
|                | 901-930 |          | T |          | U |
|                | 901-935 |          | T |          | U |
|                | 901-940 |          | T |          | U |
|                | 901-945 |          | T |          | U |
|                | 901-950 |          | T |          | U |
|                | 901-955 |          | T |          | U |
|                | 901-960 |          | T |          | U |
|                | 901-965 |          | T |          | U |
|                | 901-970 |          | T |          | U |
|                | 901-975 |          | T |          | U |
|                | 901-980 |          | T |          | U |
|                | 901-985 |          | T |          | U |
|                | 901-990 |          | T |          | U |
|                | 901-995 |          | T |          | U |
|                | 901-9MM |          | T |          | U |
|                | 902-020 |          | T |          | U |
|                | 902-030 |          | T |          | U |
|                | 902-035 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 902-040   | Old Rev. | T | New Rev. | U |
|                | 902-045   |          | T |          | U |
|                | 902-050   |          | T |          | U |
|                | 902-055   |          | T |          | U |
|                | 902-060   |          | T |          | U |
|                | 902-065   |          | T |          | U |
|                | 902-070   |          | T |          | U |
|                | 902-075   |          | T |          | U |
|                | 902-080   |          | T |          | U |
|                | 902-085   |          | T |          | U |
|                | 902-090   |          | T |          | U |
|                | 902-095   |          | T |          | U |
|                | 902-1.000 |          | T |          | U |
|                | 902-1.100 |          | T |          | U |
|                | 902-1.125 |          | T |          | U |
|                | 902-1.250 |          | T |          | U |
|                | 902-100   |          | T |          | U |
|                | 902-105   |          | T |          | U |
|                | 902-10MM  |          | T |          | U |
|                | 902-110   |          | T |          | U |
|                | 902-115   |          | T |          | U |
|                | 902-11MM  |          | T |          | U |
|                | 902-120   |          | T |          | U |
|                | 902-125   |          | T |          | U |
|                | 902-12MM  |          | T |          | U |
|                | 902-130   |          | T |          | U |
|                | 902-135   |          | T |          | U |
|                | 902-13MM  |          | T |          | U |
|                | 902-140   |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 902-145  | Old Rev. | T | New Rev. | U |
|                | 902-150  |          | T |          | U |
|                | 902-155  |          | T |          | U |
|                | 902-15MM |          | T |          | U |
|                | 902-160  |          | T |          | U |
|                | 902-165  |          | T |          | U |
|                | 902-16MM |          | T |          | U |
|                | 902-170  |          | T |          | U |
|                | 902-175  |          | T |          | U |
|                | 902-17MM |          | T |          | U |
|                | 902-180  |          | T |          | U |
|                | 902-185  |          | T |          | U |
|                | 902-18MM |          | T |          | U |
|                | 902-190  |          | T |          | U |
|                | 902-195  |          | T |          | U |
|                | 902-19MM |          | T |          | U |
|                | 902-1MM  |          | T |          | U |
|                | 902-200  |          | T |          | U |
|                | 902-205  |          | T |          | U |
|                | 902-20MM |          | T |          | U |
|                | 902-210  |          | T |          | U |
|                | 902-215  |          | T |          | U |
|                | 902-220  |          | T |          | U |
|                | 902-225  |          | T |          | U |
|                | 902-230  |          | T |          | U |
|                | 902-235  |          | T |          | U |
|                | 902-240  |          | T |          | U |
|                | 902-245  |          | T |          | U |
|                | 902-250  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 902-255  | Old Rev. | T | New Rev. | U |
|                | 902-260  |          | T |          | U |
|                | 902-265  |          | T |          | U |
|                | 902-270  |          | T |          | U |
|                | 902-275  |          | T |          | U |
|                | 902-280  |          | T |          | U |
|                | 902-285  |          | T |          | U |
|                | 902-290  |          | T |          | U |
|                | 902-295  |          | T |          | U |
|                | 902-2MM  |          | T |          | U |
|                | 902-300  |          | T |          | U |
|                | 902-305  |          | T |          | U |
|                | 902-310  |          | T |          | U |
|                | 902-312  |          | T |          | U |
|                | 902-315  |          | T |          | U |
|                | 902-320  |          | T |          | U |
|                | 902-325  |          | T |          | U |
|                | 902-32MM |          | T |          | U |
|                | 902-330  |          | T |          | U |
|                | 902-335  |          | T |          | U |
|                | 902-340  |          | T |          | U |
|                | 902-345  |          | T |          | U |
|                | 902-350  |          | T |          | U |
|                | 902-355  |          | T |          | U |
|                | 902-360  |          | T |          | U |
|                | 902-365  |          | T |          | U |
|                | 902-370  |          | T |          | U |
|                | 902-375  |          | T |          | U |
|                | 902-380  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 902-385 | Old Rev. | T | New Rev. | U |
|                | 902-390 |          | T |          | U |
|                | 902-395 |          | T |          | U |
|                | 902-3MM |          | T |          | U |
|                | 902-400 |          | T |          | U |
|                | 902-405 |          | T |          | U |
|                | 902-410 |          | T |          | U |
|                | 902-415 |          | T |          | U |
|                | 902-420 |          | T |          | U |
|                | 902-425 |          | T |          | U |
|                | 902-430 |          | T |          | U |
|                | 902-435 |          | T |          | U |
|                | 902-437 |          | T |          | U |
|                | 902-440 |          | T |          | U |
|                | 902-445 |          | T |          | U |
|                | 902-450 |          | T |          | U |
|                | 902-455 |          | T |          | U |
|                | 902-460 |          | T |          | U |
|                | 902-465 |          | T |          | U |
|                | 902-470 |          | T |          | U |
|                | 902-475 |          | T |          | U |
|                | 902-480 |          | T |          | U |
|                | 902-485 |          | T |          | U |
|                | 902-490 |          | T |          | U |
|                | 902-495 |          | T |          | U |
|                | 902-4MM |          | T |          | U |
|                | 902-500 |          | T |          | U |
|                | 902-505 |          | T |          | U |
|                | 902-510 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 902-515 | Old Rev. | T | New Rev. | U |
|                | 902-520 |          | T |          | U |
|                | 902-525 |          | T |          | U |
|                | 902-530 |          | T |          | U |
|                | 902-535 |          | T |          | U |
|                | 902-540 |          | T |          | U |
|                | 902-545 |          | T |          | U |
|                | 902-550 |          | T |          | U |
|                | 902-555 |          | T |          | U |
|                | 902-560 |          | T |          | U |
|                | 902-565 |          | T |          | U |
|                | 902-570 |          | T |          | U |
|                | 902-575 |          | T |          | U |
|                | 902-580 |          | T |          | U |
|                | 902-585 |          | T |          | U |
|                | 902-590 |          | T |          | U |
|                | 902-595 |          | T |          | U |
|                | 902-5MM |          | T |          | U |
|                | 902-600 |          | T |          | U |
|                | 902-605 |          | T |          | U |
|                | 902-610 |          | T |          | U |
|                | 902-615 |          | T |          | U |
|                | 902-620 |          | T |          | U |
|                | 902-625 |          | T |          | U |
|                | 902-630 |          | T |          | U |
|                | 902-635 |          | T |          | U |
|                | 902-640 |          | T |          | U |
|                | 902-645 |          | T |          | U |
|                | 902-650 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 902-655 | Old Rev. | T | New Rev. | U |
|                | 902-660 |          | T |          | U |
|                | 902-665 |          | T |          | U |
|                | 902-670 |          | T |          | U |
|                | 902-675 |          | T |          | U |
|                | 902-680 |          | T |          | U |
|                | 902-685 |          | T |          | U |
|                | 902-690 |          | T |          | U |
|                | 902-695 |          | T |          | U |
|                | 902-6MM |          | T |          | U |
|                | 902-700 |          | T |          | U |
|                | 902-705 |          | T |          | U |
|                | 902-710 |          | T |          | U |
|                | 902-715 |          | T |          | U |
|                | 902-720 |          | T |          | U |
|                | 902-725 |          | T |          | U |
|                | 902-730 |          | T |          | U |
|                | 902-735 |          | T |          | U |
|                | 902-740 |          | T |          | U |
|                | 902-745 |          | T |          | U |
|                | 902-750 |          | T |          | U |
|                | 902-755 |          | T |          | U |
|                | 902-760 |          | T |          | U |
|                | 902-765 |          | T |          | U |
|                | 902-770 |          | T |          | U |
|                | 902-775 |          | T |          | U |
|                | 902-780 |          | T |          | U |
|                | 902-785 |          | T |          | U |
|                | 902-790 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 902-795 | Old Rev. | T | New Rev. | U |
|                | 902-7MM |          | T |          | U |
|                | 902-800 |          | T |          | U |
|                | 902-805 |          | T |          | U |
|                | 902-810 |          | T |          | U |
|                | 902-815 |          | T |          | U |
|                | 902-820 |          | T |          | U |
|                | 902-825 |          | T |          | U |
|                | 902-830 |          | T |          | U |
|                | 902-835 |          | T |          | U |
|                | 902-840 |          | T |          | U |
|                | 902-845 |          | T |          | U |
|                | 902-850 |          | T |          | U |
|                | 902-855 |          | T |          | U |
|                | 902-860 |          | T |          | U |
|                | 902-865 |          | T |          | U |
|                | 902-870 |          | T |          | U |
|                | 902-875 |          | T |          | U |
|                | 902-880 |          | T |          | U |
|                | 902-885 |          | T |          | U |
|                | 902-890 |          | T |          | U |
|                | 902-8MM |          | T |          | U |
|                | 902-900 |          | T |          | U |
|                | 902-905 |          | T |          | U |
|                | 902-910 |          | T |          | U |
|                | 902-915 |          | T |          | U |
|                | 902-920 |          | T |          | U |
|                | 902-925 |          | T |          | U |
|                | 902-930 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 902-935    | Old Rev. | T | New Rev. | U |
|                | 902-940    |          | T |          | U |
|                | 902-945    |          | T |          | U |
|                | 902-950    |          | T |          | U |
|                | 902-955    |          | T |          | U |
|                | 902-960    |          | T |          | U |
|                | 902-965    |          | T |          | U |
|                | 902-970    |          | T |          | U |
|                | 902-975    |          | T |          | U |
|                | 902-980    |          | T |          | U |
|                | 902-985    |          | T |          | U |
|                | 902-990    |          | T |          | U |
|                | 902-995    |          | T |          | U |
|                | 902-9MM    |          | T |          | U |
|                | 903-030    |          | T |          | U |
|                | 903-035    |          | T |          | U |
|                | 903-040    |          | T |          | U |
|                | 903-045    |          | T |          | U |
|                | 903-050    |          | T |          | U |
|                | 903-055    |          | T |          | U |
|                | 903-060    |          | T |          | U |
|                | 903-065    |          | T |          | U |
|                | 903-065 BK |          | T |          | U |
|                | 903-070    |          | T |          | U |
|                | 903-075    |          | T |          | U |
|                | 903-080    |          | T |          | U |
|                | 903-085    |          | T |          | U |
|                | 903-090    |          | T |          | U |
|                | 903-095    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 903-1.000  | Old Rev. | T | New Rev. | U |
|                | 903-1.060  |          | T |          | U |
|                | 903-1.065  |          | T |          | U |
|                | 903-1.125  |          | T |          | U |
|                | 903-1.250  |          | T |          | U |
|                | 903-100    |          | T |          | U |
|                | 903-100 BK |          | T |          | U |
|                | 903-105    |          | T |          | U |
|                | 903-10MM   |          | T |          | U |
|                | 903-110    |          | T |          | U |
|                | 903-115    |          | T |          | U |
|                | 903-11MM   |          | T |          | U |
|                | 903-120    |          | T |          | U |
|                | 903-125    |          | T |          | U |
|                | 903-12MM   |          | T |          | U |
|                | 903-130    |          | T |          | U |
|                | 903-135    |          | T |          | U |
|                | 903-140    |          | T |          | U |
|                | 903-145    |          | T |          | U |
|                | 903-14MM   |          | T |          | U |
|                | 903-150    |          | T |          | U |
|                | 903-155    |          | T |          | U |
|                | 903-15MM   |          | T |          | U |
|                | 903-160    |          | T |          | U |
|                | 903-165    |          | T |          | U |
|                | 903-16MM   |          | T |          | U |
|                | 903-170    |          | T |          | U |
|                | 903-175    |          | T |          | U |
|                | 903-180    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 903-185  | Old Rev. | T | New Rev. | U |
|                | 903-187  |          | T |          | U |
|                | 903-18MM |          | T |          | U |
|                | 903-190  |          | T |          | U |
|                | 903-195  |          | T |          | U |
|                | 903-1MM  |          | T |          | U |
|                | 903-200  |          | T |          | U |
|                | 903-205  |          | T |          | U |
|                | 903-20MM |          | T |          | U |
|                | 903-210  |          | T |          | U |
|                | 903-215  |          | T |          | U |
|                | 903-220  |          | T |          | U |
|                | 903-225  |          | T |          | U |
|                | 903-230  |          | T |          | U |
|                | 903-235  |          | T |          | U |
|                | 903-240  |          | T |          | U |
|                | 903-245  |          | T |          | U |
|                | 903-24MM |          | T |          | U |
|                | 903-250  |          | T |          | U |
|                | 903-255  |          | T |          | U |
|                | 903-260  |          | T |          | U |
|                | 903-265  |          | T |          | U |
|                | 903-270  |          | T |          | U |
|                | 903-275  |          | T |          | U |
|                | 903-280  |          | T |          | U |
|                | 903-285  |          | T |          | U |
|                | 903-290  |          | T |          | U |
|                | 903-295  |          | T |          | U |
|                | 903-2MM  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 903-300 | Old Rev. | T | New Rev. | U |
|                | 903-305 |          | T |          | U |
|                | 903-310 |          | T |          | U |
|                | 903-315 |          | T |          | U |
|                | 903-320 |          | T |          | U |
|                | 903-325 |          | T |          | U |
|                | 903-330 |          | T |          | U |
|                | 903-335 |          | T |          | U |
|                | 903-340 |          | T |          | U |
|                | 903-345 |          | T |          | U |
|                | 903-350 |          | T |          | U |
|                | 903-355 |          | T |          | U |
|                | 903-360 |          | T |          | U |
|                | 903-365 |          | T |          | U |
|                | 903-370 |          | T |          | U |
|                | 903-375 |          | T |          | U |
|                | 903-380 |          | T |          | U |
|                | 903-385 |          | T |          | U |
|                | 903-390 |          | T |          | U |
|                | 903-395 |          | T |          | U |
|                | 903-3MM |          | T |          | U |
|                | 903-400 |          | T |          | U |
|                | 903-405 |          | T |          | U |
|                | 903-410 |          | T |          | U |
|                | 903-415 |          | T |          | U |
|                | 903-420 |          | T |          | U |
|                | 903-425 |          | T |          | U |
|                | 903-430 |          | T |          | U |
|                | 903-435 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 903-440 | Old Rev. | T | New Rev. | U |
|                | 903-445 |          | T |          | U |
|                | 903-450 |          | T |          | U |
|                | 903-455 |          | T |          | U |
|                | 903-460 |          | T |          | U |
|                | 903-465 |          | T |          | U |
|                | 903-470 |          | T |          | U |
|                | 903-475 |          | T |          | U |
|                | 903-480 |          | T |          | U |
|                | 903-485 |          | T |          | U |
|                | 903-490 |          | T |          | U |
|                | 903-495 |          | T |          | U |
|                | 903-4MM |          | T |          | U |
|                | 903-500 |          | T |          | U |
|                | 903-505 |          | T |          | U |
|                | 903-510 |          | T |          | U |
|                | 903-515 |          | T |          | U |
|                | 903-520 |          | T |          | U |
|                | 903-525 |          | T |          | U |
|                | 903-530 |          | T |          | U |
|                | 903-535 |          | T |          | U |
|                | 903-540 |          | T |          | U |
|                | 903-545 |          | T |          | U |
|                | 903-550 |          | T |          | U |
|                | 903-555 |          | T |          | U |
|                | 903-560 |          | T |          | U |
|                | 903-565 |          | T |          | U |
|                | 903-570 |          | T |          | U |
|                | 903-575 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 903-580 | Old Rev. | T | New Rev. | U |
|                | 903-585 |          | T |          | U |
|                | 903-590 |          | T |          | U |
|                | 903-595 |          | T |          | U |
|                | 903-5MM |          | T |          | U |
|                | 903-600 |          | T |          | U |
|                | 903-605 |          | T |          | U |
|                | 903-610 |          | T |          | U |
|                | 903-615 |          | T |          | U |
|                | 903-620 |          | T |          | U |
|                | 903-625 |          | T |          | U |
|                | 903-630 |          | T |          | U |
|                | 903-635 |          | T |          | U |
|                | 903-640 |          | T |          | U |
|                | 903-645 |          | T |          | U |
|                | 903-650 |          | T |          | U |
|                | 903-655 |          | T |          | U |
|                | 903-660 |          | T |          | U |
|                | 903-665 |          | T |          | U |
|                | 903-670 |          | T |          | U |
|                | 903-675 |          | T |          | U |
|                | 903-680 |          | T |          | U |
|                | 903-685 |          | T |          | U |
|                | 903-690 |          | T |          | U |
|                | 903-695 |          | T |          | U |
|                | 903-6MM |          | T |          | U |
|                | 903-700 |          | T |          | U |
|                | 903-705 |          | T |          | U |
|                | 903-710 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 903-715 | Old Rev. | T | New Rev. | U |
|                | 903-720 |          | T |          | U |
|                | 903-725 |          | T |          | U |
|                | 903-730 |          | T |          | U |
|                | 903-735 |          | T |          | U |
|                | 903-740 |          | T |          | U |
|                | 903-745 |          | T |          | U |
|                | 903-750 |          | T |          | U |
|                | 903-755 |          | T |          | U |
|                | 903-760 |          | T |          | U |
|                | 903-765 |          | T |          | U |
|                | 903-770 |          | T |          | U |
|                | 903-775 |          | T |          | U |
|                | 903-780 |          | T |          | U |
|                | 903-785 |          | T |          | U |
|                | 903-790 |          | T |          | U |
|                | 903-795 |          | T |          | U |
|                | 903-7MM |          | T |          | U |
|                | 903-800 |          | T |          | U |
|                | 903-805 |          | T |          | U |
|                | 903-810 |          | T |          | U |
|                | 903-815 |          | T |          | U |
|                | 903-820 |          | T |          | U |
|                | 903-825 |          | T |          | U |
|                | 903-830 |          | T |          | U |
|                | 903-835 |          | T |          | U |
|                | 903-840 |          | T |          | U |
|                | 903-845 |          | T |          | U |
|                | 903-850 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 903-855   | Old Rev. | T | New Rev. | U |
|                | 903-860   |          | T |          | U |
|                | 903-865   |          | T |          | U |
|                | 903-870   |          | T |          | U |
|                | 903-875   |          | T |          | U |
|                | 903-880   |          | T |          | U |
|                | 903-885   |          | T |          | U |
|                | 903-890   |          | T |          | U |
|                | 903-895   |          | T |          | U |
|                | 903-8MM   |          | T |          | U |
|                | 903-900   |          | T |          | U |
|                | 903-935   |          | T |          | U |
|                | 903-940   |          | T |          | U |
|                | 903-995   |          | T |          | U |
|                | 903-9MM   |          | T |          | U |
|                | 90380A331 |          | T |          | U |
|                | 904-020   |          | T |          | U |
|                | 904-030   |          | T |          | U |
|                | 904-035   |          | T |          | U |
|                | 904-040   |          | T |          | U |
|                | 904-045   |          | T |          | U |
|                | 904-050   |          | T |          | U |
|                | 904-055   |          | T |          | U |
|                | 904-060   |          | T |          | U |
|                | 904-065   |          | T |          | U |
|                | 904-070   |          | T |          | U |
|                | 904-075   |          | T |          | U |
|                | 904-080   |          | T |          | U |
|                | 904-085   |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 904-090   | Old Rev. | T | New Rev. | U |
|                | 904-095   |          | T |          | U |
|                | 904-1.000 |          | T |          | U |
|                | 904-1.065 |          | T |          | U |
|                | 904-1.125 |          | T |          | U |
|                | 904-1.250 |          | T |          | U |
|                | 904-100   |          | T |          | U |
|                | 904-105   |          | T |          | U |
|                | 904-10MM  |          | T |          | U |
|                | 904-110   |          | T |          | U |
|                | 904-115   |          | T |          | U |
|                | 904-11MM  |          | T |          | U |
|                | 904-120   |          | T |          | U |
|                | 904-125   |          | T |          | U |
|                | 904-12MM  |          | T |          | U |
|                | 904-130   |          | T |          | U |
|                | 904-135   |          | T |          | U |
|                | 904-13MM  |          | T |          | U |
|                | 904-140   |          | T |          | U |
|                | 904-150   |          | T |          | U |
|                | 904-155   |          | T |          | U |
|                | 904-15MM  |          | T |          | U |
|                | 904-160   |          | T |          | U |
|                | 904-165   |          | T |          | U |
|                | 904-170   |          | T |          | U |
|                | 904-175   |          | T |          | U |
|                | 904-180   |          | T |          | U |
|                | 904-185   |          | T |          | U |
|                | 904-187   |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 904-190  | Old Rev. | T | New Rev. | U |
|                | 904-195  |          | T |          | U |
|                | 904-1MM  |          | T |          | U |
|                | 904-200  |          | T |          | U |
|                | 904-205  |          | T |          | U |
|                | 904-20MM |          | T |          | U |
|                | 904-210  |          | T |          | U |
|                | 904-220  |          | T |          | U |
|                | 904-225  |          | T |          | U |
|                | 904-22MM |          | T |          | U |
|                | 904-230  |          | T |          | U |
|                | 904-235  |          | T |          | U |
|                | 904-240  |          | T |          | U |
|                | 904-245  |          | T |          | U |
|                | 904-250  |          | T |          | U |
|                | 904-255  |          | T |          | U |
|                | 904-260  |          | T |          | U |
|                | 904-270  |          | T |          | U |
|                | 904-275  |          | T |          | U |
|                | 904-280  |          | T |          | U |
|                | 904-290  |          | T |          | U |
|                | 904-295  |          | T |          | U |
|                | 904-2MM  |          | T |          | U |
|                | 904-300  |          | T |          | U |
|                | 904-310  |          | T |          | U |
|                | 904-315  |          | T |          | U |
|                | 904-320  |          | T |          | U |
|                | 904-325  |          | T |          | U |
|                | 904-330  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 904-335    | Old Rev. | T | New Rev. | U |
|                | 904-340    |          | T |          | U |
|                | 904-345    |          | T |          | U |
|                | 904-350    |          | T |          | U |
|                | 904-355    |          | T |          | U |
|                | 904-360    |          | T |          | U |
|                | 904-370    |          | T |          | U |
|                | 904-375    |          | T |          | U |
|                | 904-375 BK |          | T |          | U |
|                | 904-380    |          | T |          | U |
|                | 904-385    |          | T |          | U |
|                | 904-390    |          | T |          | U |
|                | 904-395    |          | T |          | U |
|                | 904-3MM    |          | T |          | U |
|                | 904-400    |          | T |          | U |
|                | 904-410    |          | T |          | U |
|                | 904-415    |          | T |          | U |
|                | 904-425    |          | T |          | U |
|                | 904-435    |          | T |          | U |
|                | 904-440    |          | T |          | U |
|                | 904-450    |          | T |          | U |
|                | 904-460    |          | T |          | U |
|                | 904-470    |          | T |          | U |
|                | 904-495    |          | T |          | U |
|                | 904-4MM    |          | T |          | U |
|                | 904-500    |          | T |          | U |
|                | 904-510    |          | T |          | U |
|                | 904-550    |          | T |          | U |
|                | 904-560    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 904-565 | Old Rev. | T | New Rev. | U |
|                | 904-570 |          | T |          | U |
|                | 904-5MM |          | T |          | U |
|                | 904-600 |          | T |          | U |
|                | 904-620 |          | T |          | U |
|                | 904-625 |          | T |          | U |
|                | 904-640 |          | T |          | U |
|                | 904-645 |          | T |          | U |
|                | 904-650 |          | T |          | U |
|                | 904-680 |          | T |          | U |
|                | 904-685 |          | T |          | U |
|                | 904-690 |          | T |          | U |
|                | 904-6MM |          | T |          | U |
|                | 904-710 |          | T |          | U |
|                | 904-750 |          | T |          | U |
|                | 904-755 |          | T |          | U |
|                | 904-780 |          | T |          | U |
|                | 904-7MM |          | T |          | U |
|                | 904-800 |          | T |          | U |
|                | 904-810 |          | T |          | U |
|                | 904-815 |          | T |          | U |
|                | 904-845 |          | T |          | U |
|                | 904-850 |          | T |          | U |
|                | 904-875 |          | T |          | U |
|                | 904-8MM |          | T |          | U |
|                | 904-940 |          | T |          | U |
|                | 904-975 |          | T |          | U |
|                | 904-9MM |          | T |          | U |
|                | 905-030 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 905-035    | Old Rev. | T | New Rev. | U |
|                | 905-040    |          | T |          | U |
|                | 905-045    |          | T |          | U |
|                | 905-050    |          | T |          | U |
|                | 905-050 BK |          | T |          | U |
|                | 905-055    |          | T |          | U |
|                | 905-060    |          | T |          | U |
|                | 905-065    |          | T |          | U |
|                | 905-070    |          | T |          | U |
|                | 905-070 BE |          | T |          | U |
|                | 905-070 RD |          | T |          | U |
|                | 905-075    |          | T |          | U |
|                | 905-080    |          | T |          | U |
|                | 905-085    |          | T |          | U |
|                | 905-090    |          | T |          | U |
|                | 905-095    |          | T |          | U |
|                | 905-1.000  |          | T |          | U |
|                | 905-1.015  |          | T |          | U |
|                | 905-1.030  |          | T |          | U |
|                | 905-1.050  |          | T |          | U |
|                | 905-1.060  |          | T |          | U |
|                | 905-1.065  |          | T |          | U |
|                | 905-1.070  |          | T |          | U |
|                | 905-1.075  |          | T |          | U |
|                | 905-1.100  |          | T |          | U |
|                | 905-1.120  |          | T |          | U |
|                | 905-1.125  |          | T |          | U |
|                | 905-1.130  |          | T |          | U |
|                | 905-1.150  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |              |          |   |          |   |
|----------------|--------------|----------|---|----------|---|
| Parts Affected | 905-1.150 BK | Old Rev. | T | New Rev. | U |
|                | 905-1.160    |          | T |          | U |
|                | 905-1.170    |          | T |          | U |
|                | 905-1.175    |          | T |          | U |
|                | 905-1.180    |          | T |          | U |
|                | 905-1.185    |          | T |          | U |
|                | 905-1.190    |          | T |          | U |
|                | 905-1.210    |          | T |          | U |
|                | 905-1.250    |          | T |          | U |
|                | 905-1.310    |          | T |          | U |
|                | 905-1.335    |          | T |          | U |
|                | 905-1.375    |          | T |          | U |
|                | 905-1.500    |          | T |          | U |
|                | 905-1.560    |          | T |          | U |
|                | 905-100      |          | T |          | U |
|                | 905-105      |          | T |          | U |
|                | 905-10MM     |          | T |          | U |
|                | 905-110      |          | T |          | U |
|                | 905-115      |          | T |          | U |
|                | 905-11MM     |          | T |          | U |
|                | 905-120      |          | T |          | U |
|                | 905-125      |          | T |          | U |
|                | 905-12MM     |          | T |          | U |
|                | 905-130      |          | T |          | U |
|                | 905-135      |          | T |          | U |
|                | 905-140      |          | T |          | U |
|                | 905-140 BE   |          | T |          | U |
|                | 905-140 RD   |          | T |          | U |
|                | 905-145      |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 905-14MM   | Old Rev. | T | New Rev. | U |
|                | 905-150    |          | T |          | U |
|                | 905-155    |          | T |          | U |
|                | 905-15MM   |          | T |          | U |
|                | 905-160    |          | T |          | U |
|                | 905-165    |          | T |          | U |
|                | 905-16MM   |          | T |          | U |
|                | 905-170    |          | T |          | U |
|                | 905-175    |          | T |          | U |
|                | 905-175 BK |          | T |          | U |
|                | 905-17MM   |          | T |          | U |
|                | 905-180    |          | T |          | U |
|                | 905-185    |          | T |          | U |
|                | 905-190    |          | T |          | U |
|                | 905-195    |          | T |          | U |
|                | 905-19MM   |          | T |          | U |
|                | 905-1MM    |          | T |          | U |
|                | 905-200    |          | T |          | U |
|                | 905-205    |          | T |          | U |
|                | 905-20MM   |          | T |          | U |
|                | 905-210    |          | T |          | U |
|                | 905-215    |          | T |          | U |
|                | 905-21MM   |          | T |          | U |
|                | 905-220    |          | T |          | U |
|                | 905-225    |          | T |          | U |
|                | 905-22MM   |          | T |          | U |
|                | 905-230    |          | T |          | U |
|                | 905-235    |          | T |          | U |
|                | 905-240    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 905-245    | Old Rev. | T | New Rev. | U |
|                | 905-250    |          | T |          | U |
|                | 905-250 BK |          | T |          | U |
|                | 905-255    |          | T |          | U |
|                | 905-260    |          | T |          | U |
|                | 905-265    |          | T |          | U |
|                | 905-270    |          | T |          | U |
|                | 905-275    |          | T |          | U |
|                | 905-280    |          | T |          | U |
|                | 905-285    |          | T |          | U |
|                | 905-28MM   |          | T |          | U |
|                | 905-290    |          | T |          | U |
|                | 905-295    |          | T |          | U |
|                | 905-2MM    |          | T |          | U |
|                | 905-300    |          | T |          | U |
|                | 905-300 BK |          | T |          | U |
|                | 905-305    |          | T |          | U |
|                | 905-310    |          | T |          | U |
|                | 905-315    |          | T |          | U |
|                | 905-320    |          | T |          | U |
|                | 905-325    |          | T |          | U |
|                | 905-330    |          | T |          | U |
|                | 905-335    |          | T |          | U |
|                | 905-340    |          | T |          | U |
|                | 905-345    |          | T |          | U |
|                | 905-350    |          | T |          | U |
|                | 905-355    |          | T |          | U |
|                | 905-360    |          | T |          | U |
|                | 905-365    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 905-370 | Old Rev. | T | New Rev. | U |
|                | 905-375 |          | T |          | U |
|                | 905-380 |          | T |          | U |
|                | 905-385 |          | T |          | U |
|                | 905-390 |          | T |          | U |
|                | 905-395 |          | T |          | U |
|                | 905-3MM |          | T |          | U |
|                | 905-400 |          | T |          | U |
|                | 905-405 |          | T |          | U |
|                | 905-410 |          | T |          | U |
|                | 905-415 |          | T |          | U |
|                | 905-420 |          | T |          | U |
|                | 905-425 |          | T |          | U |
|                | 905-430 |          | T |          | U |
|                | 905-435 |          | T |          | U |
|                | 905-440 |          | T |          | U |
|                | 905-445 |          | T |          | U |
|                | 905-450 |          | T |          | U |
|                | 905-455 |          | T |          | U |
|                | 905-460 |          | T |          | U |
|                | 905-465 |          | T |          | U |
|                | 905-470 |          | T |          | U |
|                | 905-475 |          | T |          | U |
|                | 905-480 |          | T |          | U |
|                | 905-485 |          | T |          | U |
|                | 905-490 |          | T |          | U |
|                | 905-495 |          | T |          | U |
|                | 905-4MM |          | T |          | U |
|                | 905-500 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 905-505 | Old Rev. | T | New Rev. | U |
|                | 905-510 |          | T |          | U |
|                | 905-515 |          | T |          | U |
|                | 905-520 |          | T |          | U |
|                | 905-525 |          | T |          | U |
|                | 905-530 |          | T |          | U |
|                | 905-535 |          | T |          | U |
|                | 905-540 |          | T |          | U |
|                | 905-545 |          | T |          | U |
|                | 905-550 |          | T |          | U |
|                | 905-555 |          | T |          | U |
|                | 905-560 |          | T |          | U |
|                | 905-565 |          | T |          | U |
|                | 905-570 |          | T |          | U |
|                | 905-575 |          | T |          | U |
|                | 905-580 |          | T |          | U |
|                | 905-585 |          | T |          | U |
|                | 905-590 |          | T |          | U |
|                | 905-595 |          | T |          | U |
|                | 905-5MM |          | T |          | U |
|                | 905-600 |          | T |          | U |
|                | 905-605 |          | T |          | U |
|                | 905-610 |          | T |          | U |
|                | 905-615 |          | T |          | U |
|                | 905-620 |          | T |          | U |
|                | 905-625 |          | T |          | U |
|                | 905-630 |          | T |          | U |
|                | 905-635 |          | T |          | U |
|                | 905-640 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 905-645 | Old Rev. | T | New Rev. | U |
|                | 905-650 |          | T |          | U |
|                | 905-655 |          | T |          | U |
|                | 905-660 |          | T |          | U |
|                | 905-665 |          | T |          | U |
|                | 905-670 |          | T |          | U |
|                | 905-675 |          | T |          | U |
|                | 905-680 |          | T |          | U |
|                | 905-685 |          | T |          | U |
|                | 905-690 |          | T |          | U |
|                | 905-695 |          | T |          | U |
|                | 905-6MM |          | T |          | U |
|                | 905-700 |          | T |          | U |
|                | 905-705 |          | T |          | U |
|                | 905-710 |          | T |          | U |
|                | 905-715 |          | T |          | U |
|                | 905-720 |          | T |          | U |
|                | 905-725 |          | T |          | U |
|                | 905-730 |          | T |          | U |
|                | 905-735 |          | T |          | U |
|                | 905-740 |          | T |          | U |
|                | 905-745 |          | T |          | U |
|                | 905-750 |          | T |          | U |
|                | 905-755 |          | T |          | U |
|                | 905-760 |          | T |          | U |
|                | 905-765 |          | T |          | U |
|                | 905-770 |          | T |          | U |
|                | 905-775 |          | T |          | U |
|                | 905-780 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 905-785 | Old Rev. | T | New Rev. | U |
|                | 905-790 |          | T |          | U |
|                | 905-795 |          | T |          | U |
|                | 905-7MM |          | T |          | U |
|                | 905-800 |          | T |          | U |
|                | 905-805 |          | T |          | U |
|                | 905-810 |          | T |          | U |
|                | 905-815 |          | T |          | U |
|                | 905-820 |          | T |          | U |
|                | 905-825 |          | T |          | U |
|                | 905-830 |          | T |          | U |
|                | 905-835 |          | T |          | U |
|                | 905-840 |          | T |          | U |
|                | 905-845 |          | T |          | U |
|                | 905-850 |          | T |          | U |
|                | 905-855 |          | T |          | U |
|                | 905-860 |          | T |          | U |
|                | 905-865 |          | T |          | U |
|                | 905-870 |          | T |          | U |
|                | 905-875 |          | T |          | U |
|                | 905-880 |          | T |          | U |
|                | 905-885 |          | T |          | U |
|                | 905-890 |          | T |          | U |
|                | 905-895 |          | T |          | U |
|                | 905-8MM |          | T |          | U |
|                | 905-900 |          | T |          | U |
|                | 905-905 |          | T |          | U |
|                | 905-910 |          | T |          | U |
|                | 905-915 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 905-920 | Old Rev. | T | New Rev. | U |
|                | 905-925 |          | T |          | U |
|                | 905-930 |          | T |          | U |
|                | 905-935 |          | T |          | U |
|                | 905-940 |          | T |          | U |
|                | 905-945 |          | T |          | U |
|                | 905-950 |          | T |          | U |
|                | 905-955 |          | T |          | U |
|                | 905-960 |          | T |          | U |
|                | 905-965 |          | T |          | U |
|                | 905-970 |          | T |          | U |
|                | 905-975 |          | T |          | U |
|                | 905-980 |          | T |          | U |
|                | 905-985 |          | T |          | U |
|                | 905-990 |          | T |          | U |
|                | 905-995 |          | T |          | U |
|                | 905-9MM |          | T |          | U |
|                | 906-030 |          | T |          | U |
|                | 906-035 |          | T |          | U |
|                | 906-040 |          | T |          | U |
|                | 906-045 |          | T |          | U |
|                | 906-050 |          | T |          | U |
|                | 906-055 |          | T |          | U |
|                | 906-060 |          | T |          | U |
|                | 906-065 |          | T |          | U |
|                | 906-070 |          | T |          | U |
|                | 906-075 |          | T |          | U |
|                | 906-080 |          | T |          | U |
|                | 906-085 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 906-090   | Old Rev. | T | New Rev. | U |
|                | 906-095   |          | T |          | U |
|                | 906-1.000 |          | T |          | U |
|                | 906-1.125 |          | T |          | U |
|                | 906-1.200 |          | T |          | U |
|                | 906-1.250 |          | T |          | U |
|                | 906-100   |          | T |          | U |
|                | 906-105   |          | T |          | U |
|                | 906-10MM  |          | T |          | U |
|                | 906-110   |          | T |          | U |
|                | 906-115   |          | T |          | U |
|                | 906-11MM  |          | T |          | U |
|                | 906-120   |          | T |          | U |
|                | 906-125   |          | T |          | U |
|                | 906-12MM  |          | T |          | U |
|                | 906-130   |          | T |          | U |
|                | 906-135   |          | T |          | U |
|                | 906-140   |          | T |          | U |
|                | 906-145   |          | T |          | U |
|                | 906-14MM  |          | T |          | U |
|                | 906-150   |          | T |          | U |
|                | 906-155   |          | T |          | U |
|                | 906-160   |          | T |          | U |
|                | 906-165   |          | T |          | U |
|                | 906-16MM  |          | T |          | U |
|                | 906-170   |          | T |          | U |
|                | 906-175   |          | T |          | U |
|                | 906-180   |          | T |          | U |
|                | 906-185   |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 906-189    | Old Rev. | T | New Rev. | U |
|                | 906-190    |          | T |          | U |
|                | 906-195    |          | T |          | U |
|                | 906-1MM    |          | T |          | U |
|                | 906-200    |          | T |          | U |
|                | 906-205    |          | T |          | U |
|                | 906-20MM   |          | T |          | U |
|                | 906-210    |          | T |          | U |
|                | 906-215    |          | T |          | U |
|                | 906-220    |          | T |          | U |
|                | 906-225    |          | T |          | U |
|                | 906-22MM   |          | T |          | U |
|                | 906-230    |          | T |          | U |
|                | 906-235    |          | T |          | U |
|                | 906-240    |          | T |          | U |
|                | 906-245    |          | T |          | U |
|                | 906-250    |          | T |          | U |
|                | 906-255    |          | T |          | U |
|                | 906-260    |          | T |          | U |
|                | 906-265    |          | T |          | U |
|                | 906-270    |          | T |          | U |
|                | 906-275    |          | T |          | U |
|                | 906-275 BK |          | T |          | U |
|                | 906-280    |          | T |          | U |
|                | 906-285    |          | T |          | U |
|                | 906-290    |          | T |          | U |
|                | 906-295    |          | T |          | U |
|                | 906-2MM    |          | T |          | U |
|                | 906-300    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 906-305    | Old Rev. | T | New Rev. | U |
|                | 906-30MM   |          | T |          | U |
|                | 906-310    |          | T |          | U |
|                | 906-315    |          | T |          | U |
|                | 906-320    |          | T |          | U |
|                | 906-325    |          | T |          | U |
|                | 906-330    |          | T |          | U |
|                | 906-335    |          | T |          | U |
|                | 906-340    |          | T |          | U |
|                | 906-345    |          | T |          | U |
|                | 906-350    |          | T |          | U |
|                | 906-355    |          | T |          | U |
|                | 906-360    |          | T |          | U |
|                | 906-365    |          | T |          | U |
|                | 906-370    |          | T |          | U |
|                | 906-375    |          | T |          | U |
|                | 906-375 BK |          | T |          | U |
|                | 906-380    |          | T |          | U |
|                | 906-385    |          | T |          | U |
|                | 906-390    |          | T |          | U |
|                | 906-395    |          | T |          | U |
|                | 906-3MM    |          | T |          | U |
|                | 906-400    |          | T |          | U |
|                | 906-405    |          | T |          | U |
|                | 906-410    |          | T |          | U |
|                | 906-415    |          | T |          | U |
|                | 906-420    |          | T |          | U |
|                | 906-425    |          | T |          | U |
|                | 906-430    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 906-435 | Old Rev. | T | New Rev. | U |
|                | 906-440 |          | T |          | U |
|                | 906-445 |          | T |          | U |
|                | 906-450 |          | T |          | U |
|                | 906-455 |          | T |          | U |
|                | 906-460 |          | T |          | U |
|                | 906-465 |          | T |          | U |
|                | 906-470 |          | T |          | U |
|                | 906-475 |          | T |          | U |
|                | 906-480 |          | T |          | U |
|                | 906-485 |          | T |          | U |
|                | 906-490 |          | T |          | U |
|                | 906-495 |          | T |          | U |
|                | 906-4MM |          | T |          | U |
|                | 906-500 |          | T |          | U |
|                | 906-505 |          | T |          | U |
|                | 906-510 |          | T |          | U |
|                | 906-515 |          | T |          | U |
|                | 906-520 |          | T |          | U |
|                | 906-525 |          | T |          | U |
|                | 906-530 |          | T |          | U |
|                | 906-535 |          | T |          | U |
|                | 906-540 |          | T |          | U |
|                | 906-545 |          | T |          | U |
|                | 906-550 |          | T |          | U |
|                | 906-555 |          | T |          | U |
|                | 906-560 |          | T |          | U |
|                | 906-565 |          | T |          | U |
|                | 906-570 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 906-575 | Old Rev. | T | New Rev. | U |
|                | 906-580 |          | T |          | U |
|                | 906-585 |          | T |          | U |
|                | 906-590 |          | T |          | U |
|                | 906-595 |          | T |          | U |
|                | 906-5MM |          | T |          | U |
|                | 906-600 |          | T |          | U |
|                | 906-605 |          | T |          | U |
|                | 906-610 |          | T |          | U |
|                | 906-615 |          | T |          | U |
|                | 906-620 |          | T |          | U |
|                | 906-625 |          | T |          | U |
|                | 906-630 |          | T |          | U |
|                | 906-635 |          | T |          | U |
|                | 906-640 |          | T |          | U |
|                | 906-645 |          | T |          | U |
|                | 906-650 |          | T |          | U |
|                | 906-655 |          | T |          | U |
|                | 906-660 |          | T |          | U |
|                | 906-665 |          | T |          | U |
|                | 906-670 |          | T |          | U |
|                | 906-675 |          | T |          | U |
|                | 906-680 |          | T |          | U |
|                | 906-685 |          | T |          | U |
|                | 906-690 |          | T |          | U |
|                | 906-695 |          | T |          | U |
|                | 906-6MM |          | T |          | U |
|                | 906-700 |          | T |          | U |
|                | 906-705 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 906-710 | Old Rev. | T | New Rev. | U |
|                | 906-715 |          | T |          | U |
|                | 906-720 |          | T |          | U |
|                | 906-725 |          | T |          | U |
|                | 906-730 |          | T |          | U |
|                | 906-735 |          | T |          | U |
|                | 906-740 |          | T |          | U |
|                | 906-745 |          | T |          | U |
|                | 906-750 |          | T |          | U |
|                | 906-755 |          | T |          | U |
|                | 906-760 |          | T |          | U |
|                | 906-765 |          | T |          | U |
|                | 906-770 |          | T |          | U |
|                | 906-775 |          | T |          | U |
|                | 906-780 |          | T |          | U |
|                | 906-785 |          | T |          | U |
|                | 906-790 |          | T |          | U |
|                | 906-795 |          | T |          | U |
|                | 906-7MM |          | T |          | U |
|                | 906-800 |          | T |          | U |
|                | 906-805 |          | T |          | U |
|                | 906-810 |          | T |          | U |
|                | 906-815 |          | T |          | U |
|                | 906-820 |          | T |          | U |
|                | 906-825 |          | T |          | U |
|                | 906-830 |          | T |          | U |
|                | 906-835 |          | T |          | U |
|                | 906-840 |          | T |          | U |
|                | 906-845 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 906-850 | Old Rev. | T | New Rev. | U |
|                | 906-855 |          | T |          | U |
|                | 906-860 |          | T |          | U |
|                | 906-865 |          | T |          | U |
|                | 906-870 |          | T |          | U |
|                | 906-875 |          | T |          | U |
|                | 906-880 |          | T |          | U |
|                | 906-885 |          | T |          | U |
|                | 906-890 |          | T |          | U |
|                | 906-895 |          | T |          | U |
|                | 906-8MM |          | T |          | U |
|                | 906-900 |          | T |          | U |
|                | 906-905 |          | T |          | U |
|                | 906-910 |          | T |          | U |
|                | 906-915 |          | T |          | U |
|                | 906-920 |          | T |          | U |
|                | 906-925 |          | T |          | U |
|                | 906-930 |          | T |          | U |
|                | 906-935 |          | T |          | U |
|                | 906-940 |          | T |          | U |
|                | 906-945 |          | T |          | U |
|                | 906-950 |          | T |          | U |
|                | 906-955 |          | T |          | U |
|                | 906-960 |          | T |          | U |
|                | 906-965 |          | T |          | U |
|                | 906-970 |          | T |          | U |
|                | 906-975 |          | T |          | U |
|                | 906-980 |          | T |          | U |
|                | 906-985 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 906-990   | Old Rev. | T | New Rev. | U |
|                | 906-995   |          | T |          | U |
|                | 906-9MM   |          | T |          | U |
|                | 907-030   |          | T |          | U |
|                | 907-035   |          | T |          | U |
|                | 907-040   |          | T |          | U |
|                | 907-045   |          | T |          | U |
|                | 907-050   |          | T |          | U |
|                | 907-055   |          | T |          | U |
|                | 907-060   |          | T |          | U |
|                | 907-065   |          | T |          | U |
|                | 907-070   |          | T |          | U |
|                | 907-075   |          | T |          | U |
|                | 907-080   |          | T |          | U |
|                | 907-085   |          | T |          | U |
|                | 907-090   |          | T |          | U |
|                | 907-095   |          | T |          | U |
|                | 907-1.000 |          | T |          | U |
|                | 907-1.115 |          | T |          | U |
|                | 907-1.125 |          | T |          | U |
|                | 907-1.150 |          | T |          | U |
|                | 907-1.155 |          | T |          | U |
|                | 907-1.200 |          | T |          | U |
|                | 907-1.250 |          | T |          | U |
|                | 907-100   |          | T |          | U |
|                | 907-105   |          | T |          | U |
|                | 907-10MM  |          | T |          | U |
|                | 907-110   |          | T |          | U |
|                | 907-115   |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 907-11MM  | Old Rev. | T | New Rev. | U |
|                | 907-120   |          | T |          | U |
|                | 907-125   |          | T |          | U |
|                | 907-12MM  |          | T |          | U |
|                | 907-130   |          | T |          | U |
|                | 907-135   |          | T |          | U |
|                | 907-13MM  |          | T |          | U |
|                | 907-140   |          | T |          | U |
|                | 907-145   |          | T |          | U |
|                | 907-14MM  |          | T |          | U |
|                | 907-150   |          | T |          | U |
|                | 907-155   |          | T |          | U |
|                | 907-15MM  |          | T |          | U |
|                | 907-160   |          | T |          | U |
|                | 907-165   |          | T |          | U |
|                | 907-16MM  |          | T |          | U |
|                | 907-170   |          | T |          | U |
|                | 907-175   |          | T |          | U |
|                | 907-17MM  |          | T |          | U |
|                | 907-180   |          | T |          | U |
|                | 907-185   |          | T |          | U |
|                | 907-18MM  |          | T |          | U |
|                | 907-190   |          | T |          | U |
|                | 907-195   |          | T |          | U |
|                | 907-19MM  |          | T |          | U |
|                | 907-1MM   |          | T |          | U |
|                | 907-2.5MM |          | T |          | U |
|                | 907-200   |          | T |          | U |
|                | 907-205   |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 907-20MM | Old Rev. | T | New Rev. | U |
|                | 907-210  |          | T |          | U |
|                | 907-215  |          | T |          | U |
|                | 907-220  |          | T |          | U |
|                | 907-225  |          | T |          | U |
|                | 907-230  |          | T |          | U |
|                | 907-235  |          | T |          | U |
|                | 907-240  |          | T |          | U |
|                | 907-245  |          | T |          | U |
|                | 907-250  |          | T |          | U |
|                | 907-255  |          | T |          | U |
|                | 907-260  |          | T |          | U |
|                | 907-265  |          | T |          | U |
|                | 907-270  |          | T |          | U |
|                | 907-275  |          | T |          | U |
|                | 907-280  |          | T |          | U |
|                | 907-285  |          | T |          | U |
|                | 907-290  |          | T |          | U |
|                | 907-295  |          | T |          | U |
|                | 907-2MM  |          | T |          | U |
|                | 907-300  |          | T |          | U |
|                | 907-305  |          | T |          | U |
|                | 907-310  |          | T |          | U |
|                | 907-315  |          | T |          | U |
|                | 907-320  |          | T |          | U |
|                | 907-325  |          | T |          | U |
|                | 907-330  |          | T |          | U |
|                | 907-335  |          | T |          | U |
|                | 907-340  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 907-345 | Old Rev. | T | New Rev. | U |
|                | 907-350 |          | T |          | U |
|                | 907-355 |          | T |          | U |
|                | 907-360 |          | T |          | U |
|                | 907-365 |          | T |          | U |
|                | 907-370 |          | T |          | U |
|                | 907-375 |          | T |          | U |
|                | 907-380 |          | T |          | U |
|                | 907-385 |          | T |          | U |
|                | 907-390 |          | T |          | U |
|                | 907-395 |          | T |          | U |
|                | 907-3MM |          | T |          | U |
|                | 907-400 |          | T |          | U |
|                | 907-405 |          | T |          | U |
|                | 907-410 |          | T |          | U |
|                | 907-415 |          | T |          | U |
|                | 907-420 |          | T |          | U |
|                | 907-425 |          | T |          | U |
|                | 907-430 |          | T |          | U |
|                | 907-435 |          | T |          | U |
|                | 907-437 |          | T |          | U |
|                | 907-440 |          | T |          | U |
|                | 907-445 |          | T |          | U |
|                | 907-450 |          | T |          | U |
|                | 907-455 |          | T |          | U |
|                | 907-460 |          | T |          | U |
|                | 907-465 |          | T |          | U |
|                | 907-470 |          | T |          | U |
|                | 907-475 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 907-480 | Old Rev. | T | New Rev. | U |
|                | 907-485 |          | T |          | U |
|                | 907-490 |          | T |          | U |
|                | 907-495 |          | T |          | U |
|                | 907-4MM |          | T |          | U |
|                | 907-500 |          | T |          | U |
|                | 907-505 |          | T |          | U |
|                | 907-510 |          | T |          | U |
|                | 907-515 |          | T |          | U |
|                | 907-520 |          | T |          | U |
|                | 907-525 |          | T |          | U |
|                | 907-530 |          | T |          | U |
|                | 907-535 |          | T |          | U |
|                | 907-540 |          | T |          | U |
|                | 907-545 |          | T |          | U |
|                | 907-550 |          | T |          | U |
|                | 907-555 |          | T |          | U |
|                | 907-560 |          | T |          | U |
|                | 907-565 |          | T |          | U |
|                | 907-570 |          | T |          | U |
|                | 907-575 |          | T |          | U |
|                | 907-580 |          | T |          | U |
|                | 907-585 |          | T |          | U |
|                | 907-590 |          | T |          | U |
|                | 907-595 |          | T |          | U |
|                | 907-5MM |          | T |          | U |
|                | 907-600 |          | T |          | U |
|                | 907-605 |          | T |          | U |
|                | 907-610 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 907-615 | Old Rev. | T | New Rev. | U |
|                | 907-620 |          | T |          | U |
|                | 907-625 |          | T |          | U |
|                | 907-630 |          | T |          | U |
|                | 907-635 |          | T |          | U |
|                | 907-640 |          | T |          | U |
|                | 907-645 |          | T |          | U |
|                | 907-650 |          | T |          | U |
|                | 907-655 |          | T |          | U |
|                | 907-660 |          | T |          | U |
|                | 907-665 |          | T |          | U |
|                | 907-670 |          | T |          | U |
|                | 907-675 |          | T |          | U |
|                | 907-680 |          | T |          | U |
|                | 907-685 |          | T |          | U |
|                | 907-690 |          | T |          | U |
|                | 907-695 |          | T |          | U |
|                | 907-6MM |          | T |          | U |
|                | 907-700 |          | T |          | U |
|                | 907-705 |          | T |          | U |
|                | 907-710 |          | T |          | U |
|                | 907-715 |          | T |          | U |
|                | 907-720 |          | T |          | U |
|                | 907-725 |          | T |          | U |
|                | 907-730 |          | T |          | U |
|                | 907-735 |          | T |          | U |
|                | 907-740 |          | T |          | U |
|                | 907-745 |          | T |          | U |
|                | 907-750 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 907-755 | Old Rev. | T | New Rev. | U |
|                | 907-760 |          | T |          | U |
|                | 907-765 |          | T |          | U |
|                | 907-770 |          | T |          | U |
|                | 907-775 |          | T |          | U |
|                | 907-780 |          | T |          | U |
|                | 907-785 |          | T |          | U |
|                | 907-790 |          | T |          | U |
|                | 907-795 |          | T |          | U |
|                | 907-7MM |          | T |          | U |
|                | 907-800 |          | T |          | U |
|                | 907-805 |          | T |          | U |
|                | 907-810 |          | T |          | U |
|                | 907-815 |          | T |          | U |
|                | 907-820 |          | T |          | U |
|                | 907-825 |          | T |          | U |
|                | 907-830 |          | T |          | U |
|                | 907-835 |          | T |          | U |
|                | 907-840 |          | T |          | U |
|                | 907-845 |          | T |          | U |
|                | 907-850 |          | T |          | U |
|                | 907-855 |          | T |          | U |
|                | 907-860 |          | T |          | U |
|                | 907-865 |          | T |          | U |
|                | 907-870 |          | T |          | U |
|                | 907-875 |          | T |          | U |
|                | 907-880 |          | T |          | U |
|                | 907-885 |          | T |          | U |
|                | 907-890 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 907-895 | Old Rev. | T | New Rev. | U |
|                | 907-8MM |          | T |          | U |
|                | 907-900 |          | T |          | U |
|                | 907-905 |          | T |          | U |
|                | 907-910 |          | T |          | U |
|                | 907-915 |          | T |          | U |
|                | 907-920 |          | T |          | U |
|                | 907-925 |          | T |          | U |
|                | 907-930 |          | T |          | U |
|                | 907-935 |          | T |          | U |
|                | 907-940 |          | T |          | U |
|                | 907-945 |          | T |          | U |
|                | 907-950 |          | T |          | U |
|                | 907-955 |          | T |          | U |
|                | 907-960 |          | T |          | U |
|                | 907-965 |          | T |          | U |
|                | 907-970 |          | T |          | U |
|                | 907-975 |          | T |          | U |
|                | 907-980 |          | T |          | U |
|                | 907-985 |          | T |          | U |
|                | 907-990 |          | T |          | U |
|                | 907-995 |          | T |          | U |
|                | 907-9MM |          | T |          | U |
|                | 908-030 |          | T |          | U |
|                | 908-035 |          | T |          | U |
|                | 908-040 |          | T |          | U |
|                | 908-045 |          | T |          | U |
|                | 908-050 |          | T |          | U |
|                | 908-055 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 908-060    | Old Rev. | T | New Rev. | U |
|                | 908-065    |          | T |          | U |
|                | 908-070    |          | T |          | U |
|                | 908-075    |          | T |          | U |
|                | 908-080    |          | T |          | U |
|                | 908-085    |          | T |          | U |
|                | 908-090    |          | T |          | U |
|                | 908-095    |          | T |          | U |
|                | 908-1.000  |          | T |          | U |
|                | 908-1.080  |          | T |          | U |
|                | 908-1.120  |          | T |          | U |
|                | 908-1.125  |          | T |          | U |
|                | 908-1.155  |          | T |          | U |
|                | 908-1.160  |          | T |          | U |
|                | 908-1.180  |          | T |          | U |
|                | 908-1.200  |          | T |          | U |
|                | 908-1.250  |          | T |          | U |
|                | 908-100    |          | T |          | U |
|                | 908-105    |          | T |          | U |
|                | 908-10MM   |          | T |          | U |
|                | 908-110    |          | T |          | U |
|                | 908-115    |          | T |          | U |
|                | 908-11MM   |          | T |          | U |
|                | 908-120    |          | T |          | U |
|                | 908-120 BK |          | T |          | U |
|                | 908-125    |          | T |          | U |
|                | 908-12MM   |          | T |          | U |
|                | 908-130    |          | T |          | U |
|                | 908-135    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 908-13MM   | Old Rev. | T | New Rev. | U |
|                | 908-140    |          | T |          | U |
|                | 908-145    |          | T |          | U |
|                | 908-14MM   |          | T |          | U |
|                | 908-150    |          | T |          | U |
|                | 908-155    |          | T |          | U |
|                | 908-15MM   |          | T |          | U |
|                | 908-160    |          | T |          | U |
|                | 908-165    |          | T |          | U |
|                | 908-170    |          | T |          | U |
|                | 908-175    |          | T |          | U |
|                | 908-17MM   |          | T |          | U |
|                | 908-180    |          | T |          | U |
|                | 908-180 BK |          | T |          | U |
|                | 908-185    |          | T |          | U |
|                | 908-18MM   |          | T |          | U |
|                | 908-190    |          | T |          | U |
|                | 908-195    |          | T |          | U |
|                | 908-19MM   |          | T |          | U |
|                | 908-1MM    |          | T |          | U |
|                | 908-2.5MM  |          | T |          | U |
|                | 908-200    |          | T |          | U |
|                | 908-200 OE |          | T |          | U |
|                | 908-205    |          | T |          | U |
|                | 908-20MM   |          | T |          | U |
|                | 908-210    |          | T |          | U |
|                | 908-215    |          | T |          | U |
|                | 908-21MM   |          | T |          | U |
|                | 908-220    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 908-225    | Old Rev. | T | New Rev. | U |
|                | 908-22MM   |          | T |          | U |
|                | 908-230    |          | T |          | U |
|                | 908-235    |          | T |          | U |
|                | 908-23MM   |          | T |          | U |
|                | 908-240    |          | T |          | U |
|                | 908-245    |          | T |          | U |
|                | 908-24MM   |          | T |          | U |
|                | 908-250    |          | T |          | U |
|                | 908-255    |          | T |          | U |
|                | 908-25MM   |          | T |          | U |
|                | 908-260    |          | T |          | U |
|                | 908-265    |          | T |          | U |
|                | 908-26MM   |          | T |          | U |
|                | 908-270    |          | T |          | U |
|                | 908-275    |          | T |          | U |
|                | 908-280    |          | T |          | U |
|                | 908-285    |          | T |          | U |
|                | 908-290    |          | T |          | U |
|                | 908-295    |          | T |          | U |
|                | 908-2MM    |          | T |          | U |
|                | 908-300    |          | T |          | U |
|                | 908-305    |          | T |          | U |
|                | 908-310    |          | T |          | U |
|                | 908-315    |          | T |          | U |
|                | 908-315 BE |          | T |          | U |
|                | 908-315 BK |          | T |          | U |
|                | 908-320    |          | T |          | U |
|                | 908-325    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 908-32MM   | Old Rev. | T | New Rev. | U |
|                | 908-330    |          | T |          | U |
|                | 908-335    |          | T |          | U |
|                | 908-335 BE |          | T |          | U |
|                | 908-340    |          | T |          | U |
|                | 908-345    |          | T |          | U |
|                | 908-350    |          | T |          | U |
|                | 908-355    |          | T |          | U |
|                | 908-360    |          | T |          | U |
|                | 908-365    |          | T |          | U |
|                | 908-370    |          | T |          | U |
|                | 908-375    |          | T |          | U |
|                | 908-380    |          | T |          | U |
|                | 908-385    |          | T |          | U |
|                | 908-390    |          | T |          | U |
|                | 908-395    |          | T |          | U |
|                | 908-3MM    |          | T |          | U |
|                | 908-400    |          | T |          | U |
|                | 908-405    |          | T |          | U |
|                | 908-410    |          | T |          | U |
|                | 908-415    |          | T |          | U |
|                | 908-415 RD |          | T |          | U |
|                | 908-420    |          | T |          | U |
|                | 908-425    |          | T |          | U |
|                | 908-430    |          | T |          | U |
|                | 908-435    |          | T |          | U |
|                | 908-440    |          | T |          | U |
|                | 908-445    |          | T |          | U |
|                | 908-450    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 908-455    | Old Rev. | T | New Rev. | U |
|                | 908-460    |          | T |          | U |
|                | 908-460 BK |          | T |          | U |
|                | 908-465    |          | T |          | U |
|                | 908-470    |          | T |          | U |
|                | 908-470 BK |          | T |          | U |
|                | 908-475    |          | T |          | U |
|                | 908-480    |          | T |          | U |
|                | 908-485    |          | T |          | U |
|                | 908-490    |          | T |          | U |
|                | 908-495    |          | T |          | U |
|                | 908-4MM    |          | T |          | U |
|                | 908-500    |          | T |          | U |
|                | 908-505    |          | T |          | U |
|                | 908-510    |          | T |          | U |
|                | 908-515    |          | T |          | U |
|                | 908-520    |          | T |          | U |
|                | 908-520 BK |          | T |          | U |
|                | 908-525    |          | T |          | U |
|                | 908-530    |          | T |          | U |
|                | 908-535    |          | T |          | U |
|                | 908-540    |          | T |          | U |
|                | 908-545    |          | T |          | U |
|                | 908-550    |          | T |          | U |
|                | 908-555    |          | T |          | U |
|                | 908-560    |          | T |          | U |
|                | 908-565    |          | T |          | U |
|                | 908-570    |          | T |          | U |
|                | 908-575    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 908-580 | Old Rev. | T | New Rev. | U |
|                | 908-585 |          | T |          | U |
|                | 908-590 |          | T |          | U |
|                | 908-595 |          | T |          | U |
|                | 908-5MM |          | T |          | U |
|                | 908-600 |          | T |          | U |
|                | 908-605 |          | T |          | U |
|                | 908-610 |          | T |          | U |
|                | 908-615 |          | T |          | U |
|                | 908-620 |          | T |          | U |
|                | 908-625 |          | T |          | U |
|                | 908-630 |          | T |          | U |
|                | 908-635 |          | T |          | U |
|                | 908-640 |          | T |          | U |
|                | 908-645 |          | T |          | U |
|                | 908-650 |          | T |          | U |
|                | 908-655 |          | T |          | U |
|                | 908-660 |          | T |          | U |
|                | 908-665 |          | T |          | U |
|                | 908-670 |          | T |          | U |
|                | 908-675 |          | T |          | U |
|                | 908-680 |          | T |          | U |
|                | 908-685 |          | T |          | U |
|                | 908-690 |          | T |          | U |
|                | 908-695 |          | T |          | U |
|                | 908-6MM |          | T |          | U |
|                | 908-700 |          | T |          | U |
|                | 908-705 |          | T |          | U |
|                | 908-710 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 908-715 | Old Rev. | T | New Rev. | U |
|                | 908-720 |          | T |          | U |
|                | 908-725 |          | T |          | U |
|                | 908-730 |          | T |          | U |
|                | 908-735 |          | T |          | U |
|                | 908-740 |          | T |          | U |
|                | 908-745 |          | T |          | U |
|                | 908-750 |          | T |          | U |
|                | 908-755 |          | T |          | U |
|                | 908-760 |          | T |          | U |
|                | 908-765 |          | T |          | U |
|                | 908-770 |          | T |          | U |
|                | 908-775 |          | T |          | U |
|                | 908-780 |          | T |          | U |
|                | 908-785 |          | T |          | U |
|                | 908-790 |          | T |          | U |
|                | 908-795 |          | T |          | U |
|                | 908-7MM |          | T |          | U |
|                | 908-800 |          | T |          | U |
|                | 908-805 |          | T |          | U |
|                | 908-810 |          | T |          | U |
|                | 908-815 |          | T |          | U |
|                | 908-820 |          | T |          | U |
|                | 908-825 |          | T |          | U |
|                | 908-830 |          | T |          | U |
|                | 908-835 |          | T |          | U |
|                | 908-840 |          | T |          | U |
|                | 908-845 |          | T |          | U |
|                | 908-850 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 908-855 | Old Rev. | T | New Rev. | U |
|                | 908-860 |          | T |          | U |
|                | 908-865 |          | T |          | U |
|                | 908-870 |          | T |          | U |
|                | 908-875 |          | T |          | U |
|                | 908-880 |          | T |          | U |
|                | 908-885 |          | T |          | U |
|                | 908-890 |          | T |          | U |
|                | 908-895 |          | T |          | U |
|                | 908-8MM |          | T |          | U |
|                | 908-900 |          | T |          | U |
|                | 908-905 |          | T |          | U |
|                | 908-910 |          | T |          | U |
|                | 908-915 |          | T |          | U |
|                | 908-920 |          | T |          | U |
|                | 908-925 |          | T |          | U |
|                | 908-930 |          | T |          | U |
|                | 908-935 |          | T |          | U |
|                | 908-940 |          | T |          | U |
|                | 908-945 |          | T |          | U |
|                | 908-950 |          | T |          | U |
|                | 908-955 |          | T |          | U |
|                | 908-960 |          | T |          | U |
|                | 908-965 |          | T |          | U |
|                | 908-970 |          | T |          | U |
|                | 908-975 |          | T |          | U |
|                | 908-980 |          | T |          | U |
|                | 908-985 |          | T |          | U |
|                | 908-990 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 908-995   | Old Rev. | T | New Rev. | U |
|                | 908-9MM   |          | T |          | U |
|                | 911-030   |          | T |          | U |
|                | 911-035   |          | T |          | U |
|                | 911-040   |          | T |          | U |
|                | 911-045   |          | T |          | U |
|                | 911-050   |          | T |          | U |
|                | 911-055   |          | T |          | U |
|                | 911-060   |          | T |          | U |
|                | 911-065   |          | T |          | U |
|                | 911-070   |          | T |          | U |
|                | 911-075   |          | T |          | U |
|                | 911-080   |          | T |          | U |
|                | 911-085   |          | T |          | U |
|                | 911-090   |          | T |          | U |
|                | 911-095   |          | T |          | U |
|                | 911-1.000 |          | T |          | U |
|                | 911-1.065 |          | T |          | U |
|                | 911-1.105 |          | T |          | U |
|                | 911-1.125 |          | T |          | U |
|                | 911-1.130 |          | T |          | U |
|                | 911-1.170 |          | T |          | U |
|                | 911-1.185 |          | T |          | U |
|                | 911-1.190 |          | T |          | U |
|                | 911-1.200 |          | T |          | U |
|                | 911-1.250 |          | T |          | U |
|                | 911-100   |          | T |          | U |
|                | 911-105   |          | T |          | U |
|                | 911-10MM  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 911-110  | Old Rev. | T | New Rev. | U |
|                | 911-115  |          | T |          | U |
|                | 911-120  |          | T |          | U |
|                | 911-125  |          | T |          | U |
|                | 911-12MM |          | T |          | U |
|                | 911-130  |          | T |          | U |
|                | 911-135  |          | T |          | U |
|                | 911-13MM |          | T |          | U |
|                | 911-140  |          | T |          | U |
|                | 911-145  |          | T |          | U |
|                | 911-14MM |          | T |          | U |
|                | 911-150  |          | T |          | U |
|                | 911-155  |          | T |          | U |
|                | 911-15MM |          | T |          | U |
|                | 911-160  |          | T |          | U |
|                | 911-165  |          | T |          | U |
|                | 911-16MM |          | T |          | U |
|                | 911-170  |          | T |          | U |
|                | 911-175  |          | T |          | U |
|                | 911-17MM |          | T |          | U |
|                | 911-180  |          | T |          | U |
|                | 911-185  |          | T |          | U |
|                | 911-18MM |          | T |          | U |
|                | 911-190  |          | T |          | U |
|                | 911-195  |          | T |          | U |
|                | 911-1MM  |          | T |          | U |
|                | 911-200  |          | T |          | U |
|                | 911-205  |          | T |          | U |
|                | 911-210  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 911-215  | Old Rev. | T | New Rev. | U |
|                | 911-220  |          | T |          | U |
|                | 911-225  |          | T |          | U |
|                | 911-230  |          | T |          | U |
|                | 911-235  |          | T |          | U |
|                | 911-240  |          | T |          | U |
|                | 911-245  |          | T |          | U |
|                | 911-250  |          | T |          | U |
|                | 911-255  |          | T |          | U |
|                | 911-260  |          | T |          | U |
|                | 911-265  |          | T |          | U |
|                | 911-270  |          | T |          | U |
|                | 911-275  |          | T |          | U |
|                | 911-280  |          | T |          | U |
|                | 911-285  |          | T |          | U |
|                | 911-28MM |          | T |          | U |
|                | 911-290  |          | T |          | U |
|                | 911-295  |          | T |          | U |
|                | 911-2MM  |          | T |          | U |
|                | 911-300  |          | T |          | U |
|                | 911-305  |          | T |          | U |
|                | 911-310  |          | T |          | U |
|                | 911-315  |          | T |          | U |
|                | 911-320  |          | T |          | U |
|                | 911-325  |          | T |          | U |
|                | 911-330  |          | T |          | U |
|                | 911-335  |          | T |          | U |
|                | 911-340  |          | T |          | U |
|                | 911-345  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 911-350  | Old Rev. | T | New Rev. | U |
|                | 911-355  |          | T |          | U |
|                | 911-360  |          | T |          | U |
|                | 911-365  |          | T |          | U |
|                | 911-370  |          | T |          | U |
|                | 911-375  |          | T |          | U |
|                | 911-380  |          | T |          | U |
|                | 911-385  |          | T |          | U |
|                | 911-390  |          | T |          | U |
|                | 911-395  |          | T |          | U |
|                | 911-3MM  |          | T |          | U |
|                | 911-400  |          | T |          | U |
|                | 911-405  |          | T |          | U |
|                | 911-40MM |          | T |          | U |
|                | 911-410  |          | T |          | U |
|                | 911-415  |          | T |          | U |
|                | 911-420  |          | T |          | U |
|                | 911-425  |          | T |          | U |
|                | 911-430  |          | T |          | U |
|                | 911-435  |          | T |          | U |
|                | 911-437  |          | T |          | U |
|                | 911-440  |          | T |          | U |
|                | 911-445  |          | T |          | U |
|                | 911-450  |          | T |          | U |
|                | 911-455  |          | T |          | U |
|                | 911-460  |          | T |          | U |
|                | 911-465  |          | T |          | U |
|                | 911-470  |          | T |          | U |
|                | 911-475  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 911-480 | Old Rev. | T | New Rev. | U |
|                | 911-485 |          | T |          | U |
|                | 911-490 |          | T |          | U |
|                | 911-495 |          | T |          | U |
|                | 911-4MM |          | T |          | U |
|                | 911-500 |          | T |          | U |
|                | 911-505 |          | T |          | U |
|                | 911-510 |          | T |          | U |
|                | 911-515 |          | T |          | U |
|                | 911-520 |          | T |          | U |
|                | 911-525 |          | T |          | U |
|                | 911-530 |          | T |          | U |
|                | 911-535 |          | T |          | U |
|                | 911-540 |          | T |          | U |
|                | 911-545 |          | T |          | U |
|                | 911-550 |          | T |          | U |
|                | 911-555 |          | T |          | U |
|                | 911-560 |          | T |          | U |
|                | 911-565 |          | T |          | U |
|                | 911-570 |          | T |          | U |
|                | 911-575 |          | T |          | U |
|                | 911-580 |          | T |          | U |
|                | 911-585 |          | T |          | U |
|                | 911-590 |          | T |          | U |
|                | 911-595 |          | T |          | U |
|                | 911-5MM |          | T |          | U |
|                | 911-600 |          | T |          | U |
|                | 911-605 |          | T |          | U |
|                | 911-610 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 911-615 | Old Rev. | T | New Rev. | U |
|                | 911-620 |          | T |          | U |
|                | 911-625 |          | T |          | U |
|                | 911-630 |          | T |          | U |
|                | 911-635 |          | T |          | U |
|                | 911-640 |          | T |          | U |
|                | 911-645 |          | T |          | U |
|                | 911-650 |          | T |          | U |
|                | 911-655 |          | T |          | U |
|                | 911-660 |          | T |          | U |
|                | 911-665 |          | T |          | U |
|                | 911-670 |          | T |          | U |
|                | 911-675 |          | T |          | U |
|                | 911-680 |          | T |          | U |
|                | 911-685 |          | T |          | U |
|                | 911-690 |          | T |          | U |
|                | 911-695 |          | T |          | U |
|                | 911-6MM |          | T |          | U |
|                | 911-700 |          | T |          | U |
|                | 911-705 |          | T |          | U |
|                | 911-710 |          | T |          | U |
|                | 911-715 |          | T |          | U |
|                | 911-720 |          | T |          | U |
|                | 911-725 |          | T |          | U |
|                | 911-730 |          | T |          | U |
|                | 911-735 |          | T |          | U |
|                | 911-740 |          | T |          | U |
|                | 911-745 |          | T |          | U |
|                | 911-750 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 911-755 | Old Rev. | T | New Rev. | U |
|                | 911-760 |          | T |          | U |
|                | 911-765 |          | T |          | U |
|                | 911-770 |          | T |          | U |
|                | 911-775 |          | T |          | U |
|                | 911-780 |          | T |          | U |
|                | 911-785 |          | T |          | U |
|                | 911-790 |          | T |          | U |
|                | 911-795 |          | T |          | U |
|                | 911-7MM |          | T |          | U |
|                | 911-800 |          | T |          | U |
|                | 911-805 |          | T |          | U |
|                | 911-810 |          | T |          | U |
|                | 911-815 |          | T |          | U |
|                | 911-820 |          | T |          | U |
|                | 911-825 |          | T |          | U |
|                | 911-830 |          | T |          | U |
|                | 911-835 |          | T |          | U |
|                | 911-840 |          | T |          | U |
|                | 911-845 |          | T |          | U |
|                | 911-850 |          | T |          | U |
|                | 911-855 |          | T |          | U |
|                | 911-860 |          | T |          | U |
|                | 911-865 |          | T |          | U |
|                | 911-870 |          | T |          | U |
|                | 911-875 |          | T |          | U |
|                | 911-880 |          | T |          | U |
|                | 911-885 |          | T |          | U |
|                | 911-890 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 911-895 | Old Rev. | T | New Rev. | U |
|                | 911-8MM |          | T |          | U |
|                | 911-900 |          | T |          | U |
|                | 911-905 |          | T |          | U |
|                | 911-910 |          | T |          | U |
|                | 911-915 |          | T |          | U |
|                | 911-920 |          | T |          | U |
|                | 911-925 |          | T |          | U |
|                | 911-930 |          | T |          | U |
|                | 911-935 |          | T |          | U |
|                | 911-940 |          | T |          | U |
|                | 911-945 |          | T |          | U |
|                | 911-950 |          | T |          | U |
|                | 911-955 |          | T |          | U |
|                | 911-960 |          | T |          | U |
|                | 911-965 |          | T |          | U |
|                | 911-970 |          | T |          | U |
|                | 911-975 |          | T |          | U |
|                | 911-980 |          | T |          | U |
|                | 911-985 |          | T |          | U |
|                | 911-990 |          | T |          | U |
|                | 911-995 |          | T |          | U |
|                | 911-9MM |          | T |          | U |
|                | 912-030 |          | T |          | U |
|                | 912-035 |          | T |          | U |
|                | 912-040 |          | T |          | U |
|                | 912-045 |          | T |          | U |
|                | 912-050 |          | T |          | U |
|                | 912-055 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 912-060    | Old Rev. | T | New Rev. | U |
|                | 912-065    |          | T |          | U |
|                | 912-070    |          | T |          | U |
|                | 912-075    |          | T |          | U |
|                | 912-080    |          | T |          | U |
|                | 912-085    |          | T |          | U |
|                | 912-090    |          | T |          | U |
|                | 912-095    |          | T |          | U |
|                | 912-1.000  |          | T |          | U |
|                | 912-1.040  |          | T |          | U |
|                | 912-1.065  |          | T |          | U |
|                | 912-1.080  |          | T |          | U |
|                | 912-1.100  |          | T |          | U |
|                | 912-1.125  |          | T |          | U |
|                | 912-1.180  |          | T |          | U |
|                | 912-1.190  |          | T |          | U |
|                | 912-1.200  |          | T |          | U |
|                | 912-1.250  |          | T |          | U |
|                | 912-10.000 |          | T |          | U |
|                | 912-100    |          | T |          | U |
|                | 912-105    |          | T |          | U |
|                | 912-10MM   |          | T |          | U |
|                | 912-110    |          | T |          | U |
|                | 912-115    |          | T |          | U |
|                | 912-120    |          | T |          | U |
|                | 912-125    |          | T |          | U |
|                | 912-12MM   |          | T |          | U |
|                | 912-130    |          | T |          | U |
|                | 912-135    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 912-13MM | Old Rev. | T | New Rev. | U |
|                | 912-140  |          | T |          | U |
|                | 912-145  |          | T |          | U |
|                | 912-150  |          | T |          | U |
|                | 912-155  |          | T |          | U |
|                | 912-15MM |          | T |          | U |
|                | 912-160  |          | T |          | U |
|                | 912-165  |          | T |          | U |
|                | 912-16MM |          | T |          | U |
|                | 912-170  |          | T |          | U |
|                | 912-175  |          | T |          | U |
|                | 912-17MM |          | T |          | U |
|                | 912-180  |          | T |          | U |
|                | 912-185  |          | T |          | U |
|                | 912-190  |          | T |          | U |
|                | 912-195  |          | T |          | U |
|                | 912-19MM |          | T |          | U |
|                | 912-1MM  |          | T |          | U |
|                | 912-200  |          | T |          | U |
|                | 912-205  |          | T |          | U |
|                | 912-20MM |          | T |          | U |
|                | 912-210  |          | T |          | U |
|                | 912-215  |          | T |          | U |
|                | 912-21MM |          | T |          | U |
|                | 912-220  |          | T |          | U |
|                | 912-225  |          | T |          | U |
|                | 912-22MM |          | T |          | U |
|                | 912-230  |          | T |          | U |
|                | 912-235  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 912-240  | Old Rev. | T | New Rev. | U |
|                | 912-245  |          | T |          | U |
|                | 912-250  |          | T |          | U |
|                | 912-255  |          | T |          | U |
|                | 912-260  |          | T |          | U |
|                | 912-265  |          | T |          | U |
|                | 912-26MM |          | T |          | U |
|                | 912-270  |          | T |          | U |
|                | 912-275  |          | T |          | U |
|                | 912-280  |          | T |          | U |
|                | 912-285  |          | T |          | U |
|                | 912-28MM |          | T |          | U |
|                | 912-290  |          | T |          | U |
|                | 912-295  |          | T |          | U |
|                | 912-2MM  |          | T |          | U |
|                | 912-300  |          | T |          | U |
|                | 912-305  |          | T |          | U |
|                | 912-310  |          | T |          | U |
|                | 912-315  |          | T |          | U |
|                | 912-320  |          | T |          | U |
|                | 912-325  |          | T |          | U |
|                | 912-32MM |          | T |          | U |
|                | 912-330  |          | T |          | U |
|                | 912-335  |          | T |          | U |
|                | 912-340  |          | T |          | U |
|                | 912-345  |          | T |          | U |
|                | 912-350  |          | T |          | U |
|                | 912-355  |          | T |          | U |
|                | 912-360  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 912-365    | Old Rev. | T | New Rev. | U |
|                | 912-370    |          | T |          | U |
|                | 912-375    |          | T |          | U |
|                | 912-380    |          | T |          | U |
|                | 912-385    |          | T |          | U |
|                | 912-390    |          | T |          | U |
|                | 912-395    |          | T |          | U |
|                | 912-3MM    |          | T |          | U |
|                | 912-400    |          | T |          | U |
|                | 912-405    |          | T |          | U |
|                | 912-410    |          | T |          | U |
|                | 912-412    |          | T |          | U |
|                | 912-415    |          | T |          | U |
|                | 912-420    |          | T |          | U |
|                | 912-425    |          | T |          | U |
|                | 912-430    |          | T |          | U |
|                | 912-430 BE |          | T |          | U |
|                | 912-435    |          | T |          | U |
|                | 912-435 BE |          | T |          | U |
|                | 912-435 BN |          | T |          | U |
|                | 912-435 GN |          | T |          | U |
|                | 912-435 OE |          | T |          | U |
|                | 912-435 PE |          | T |          | U |
|                | 912-435 RD |          | T |          | U |
|                | 912-435 VT |          | T |          | U |
|                | 912-440    |          | T |          | U |
|                | 912-445    |          | T |          | U |
|                | 912-450    |          | T |          | U |
|                | 912-450 BK |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 912-455 | Old Rev. | T | New Rev. | U |
|                | 912-460 |          | T |          | U |
|                | 912-465 |          | T |          | U |
|                | 912-470 |          | T |          | U |
|                | 912-475 |          | T |          | U |
|                | 912-480 |          | T |          | U |
|                | 912-485 |          | T |          | U |
|                | 912-490 |          | T |          | U |
|                | 912-495 |          | T |          | U |
|                | 912-4MM |          | T |          | U |
|                | 912-500 |          | T |          | U |
|                | 912-505 |          | T |          | U |
|                | 912-510 |          | T |          | U |
|                | 912-515 |          | T |          | U |
|                | 912-520 |          | T |          | U |
|                | 912-525 |          | T |          | U |
|                | 912-530 |          | T |          | U |
|                | 912-535 |          | T |          | U |
|                | 912-540 |          | T |          | U |
|                | 912-545 |          | T |          | U |
|                | 912-550 |          | T |          | U |
|                | 912-555 |          | T |          | U |
|                | 912-560 |          | T |          | U |
|                | 912-565 |          | T |          | U |
|                | 912-570 |          | T |          | U |
|                | 912-575 |          | T |          | U |
|                | 912-580 |          | T |          | U |
|                | 912-585 |          | T |          | U |
|                | 912-590 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 912-595    | Old Rev. | T | New Rev. | U |
|                | 912-5MM    |          | T |          | U |
|                | 912-600    |          | T |          | U |
|                | 912-605    |          | T |          | U |
|                | 912-610    |          | T |          | U |
|                | 912-615    |          | T |          | U |
|                | 912-620    |          | T |          | U |
|                | 912-625    |          | T |          | U |
|                | 912-630    |          | T |          | U |
|                | 912-635    |          | T |          | U |
|                | 912-640    |          | T |          | U |
|                | 912-645    |          | T |          | U |
|                | 912-650    |          | T |          | U |
|                | 912-655    |          | T |          | U |
|                | 912-660    |          | T |          | U |
|                | 912-660 BK |          | T |          | U |
|                | 912-665    |          | T |          | U |
|                | 912-670    |          | T |          | U |
|                | 912-675    |          | T |          | U |
|                | 912-680    |          | T |          | U |
|                | 912-685    |          | T |          | U |
|                | 912-690    |          | T |          | U |
|                | 912-695    |          | T |          | U |
|                | 912-6MM    |          | T |          | U |
|                | 912-700    |          | T |          | U |
|                | 912-705    |          | T |          | U |
|                | 912-710    |          | T |          | U |
|                | 912-715    |          | T |          | U |
|                | 912-720    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 912-725   | Old Rev. | T | New Rev. | U |
|                | 912-730   |          | T |          | U |
|                | 912-735   |          | T |          | U |
|                | 912-740   |          | T |          | U |
|                | 912-745   |          | T |          | U |
|                | 912-750   |          | T |          | U |
|                | 912-755   |          | T |          | U |
|                | 912-760   |          | T |          | U |
|                | 912-765   |          | T |          | U |
|                | 912-770   |          | T |          | U |
|                | 912-775   |          | T |          | U |
|                | 912-780   |          | T |          | U |
|                | 912-785   |          | T |          | U |
|                | 912-790   |          | T |          | U |
|                | 912-795   |          | T |          | U |
|                | 912-7MM   |          | T |          | U |
|                | 912-8.000 |          | T |          | U |
|                | 912-800   |          | T |          | U |
|                | 912-805   |          | T |          | U |
|                | 912-810   |          | T |          | U |
|                | 912-815   |          | T |          | U |
|                | 912-820   |          | T |          | U |
|                | 912-825   |          | T |          | U |
|                | 912-830   |          | T |          | U |
|                | 912-835   |          | T |          | U |
|                | 912-840   |          | T |          | U |
|                | 912-845   |          | T |          | U |
|                | 912-850   |          | T |          | U |
|                | 912-855   |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 912-860 | Old Rev. | T | New Rev. | U |
|                | 912-865 |          | T |          | U |
|                | 912-870 |          | T |          | U |
|                | 912-875 |          | T |          | U |
|                | 912-880 |          | T |          | U |
|                | 912-885 |          | T |          | U |
|                | 912-890 |          | T |          | U |
|                | 912-895 |          | T |          | U |
|                | 912-8MM |          | T |          | U |
|                | 912-900 |          | T |          | U |
|                | 912-905 |          | T |          | U |
|                | 912-910 |          | T |          | U |
|                | 912-915 |          | T |          | U |
|                | 912-920 |          | T |          | U |
|                | 912-925 |          | T |          | U |
|                | 912-930 |          | T |          | U |
|                | 912-935 |          | T |          | U |
|                | 912-940 |          | T |          | U |
|                | 912-945 |          | T |          | U |
|                | 912-950 |          | T |          | U |
|                | 912-955 |          | T |          | U |
|                | 912-960 |          | T |          | U |
|                | 912-965 |          | T |          | U |
|                | 912-970 |          | T |          | U |
|                | 912-975 |          | T |          | U |
|                | 912-980 |          | T |          | U |
|                | 912-985 |          | T |          | U |
|                | 912-990 |          | T |          | U |
|                | 912-995 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 912-9MM    | Old Rev. | T | New Rev. | U |
|                | 913        |          | T |          | U |
|                | 913-025    |          | T |          | U |
|                | 913-030    |          | T |          | U |
|                | 913-035    |          | T |          | U |
|                | 913-040    |          | T |          | U |
|                | 913-045    |          | T |          | U |
|                | 913-050    |          | T |          | U |
|                | 913-055    |          | T |          | U |
|                | 913-060    |          | T |          | U |
|                | 913-065    |          | T |          | U |
|                | 913-070    |          | T |          | U |
|                | 913-070 BE |          | T |          | U |
|                | 913-075    |          | T |          | U |
|                | 913-080    |          | T |          | U |
|                | 913-085    |          | T |          | U |
|                | 913-090    |          | T |          | U |
|                | 913-095    |          | T |          | U |
|                | 913-1.000  |          | T |          | U |
|                | 913-1.125  |          | T |          | U |
|                | 913-1.250  |          | T |          | U |
|                | 913-100    |          | T |          | U |
|                | 913-105    |          | T |          | U |
|                | 913-10MM   |          | T |          | U |
|                | 913-110    |          | T |          | U |
|                | 913-115    |          | T |          | U |
|                | 913-11MM   |          | T |          | U |
|                | 913-120    |          | T |          | U |
|                | 913-125    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 913-12MM | Old Rev. | T | New Rev. | U |
|                | 913-130  |          | T |          | U |
|                | 913-135  |          | T |          | U |
|                | 913-13MM |          | T |          | U |
|                | 913-140  |          | T |          | U |
|                | 913-145  |          | T |          | U |
|                | 913-14MM |          | T |          | U |
|                | 913-150  |          | T |          | U |
|                | 913-155  |          | T |          | U |
|                | 913-15MM |          | T |          | U |
|                | 913-160  |          | T |          | U |
|                | 913-165  |          | T |          | U |
|                | 913-16MM |          | T |          | U |
|                | 913-170  |          | T |          | U |
|                | 913-175  |          | T |          | U |
|                | 913-17MM |          | T |          | U |
|                | 913-180  |          | T |          | U |
|                | 913-185  |          | T |          | U |
|                | 913-18MM |          | T |          | U |
|                | 913-190  |          | T |          | U |
|                | 913-195  |          | T |          | U |
|                | 913-19MM |          | T |          | U |
|                | 913-1MM  |          | T |          | U |
|                | 913-200  |          | T |          | U |
|                | 913-205  |          | T |          | U |
|                | 913-20MM |          | T |          | U |
|                | 913-210  |          | T |          | U |
|                | 913-215  |          | T |          | U |
|                | 913-220  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 913-225 | Old Rev. | T | New Rev. | U |
|                | 913-230 |          | T |          | U |
|                | 913-235 |          | T |          | U |
|                | 913-240 |          | T |          | U |
|                | 913-245 |          | T |          | U |
|                | 913-250 |          | T |          | U |
|                | 913-255 |          | T |          | U |
|                | 913-260 |          | T |          | U |
|                | 913-265 |          | T |          | U |
|                | 913-270 |          | T |          | U |
|                | 913-275 |          | T |          | U |
|                | 913-280 |          | T |          | U |
|                | 913-285 |          | T |          | U |
|                | 913-290 |          | T |          | U |
|                | 913-295 |          | T |          | U |
|                | 913-2MM |          | T |          | U |
|                | 913-300 |          | T |          | U |
|                | 913-305 |          | T |          | U |
|                | 913-310 |          | T |          | U |
|                | 913-315 |          | T |          | U |
|                | 913-320 |          | T |          | U |
|                | 913-325 |          | T |          | U |
|                | 913-330 |          | T |          | U |
|                | 913-335 |          | T |          | U |
|                | 913-340 |          | T |          | U |
|                | 913-345 |          | T |          | U |
|                | 913-350 |          | T |          | U |
|                | 913-355 |          | T |          | U |
|                | 913-360 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 913-365 | Old Rev. | T | New Rev. | U |
|                | 913-370 |          | T |          | U |
|                | 913-375 |          | T |          | U |
|                | 913-380 |          | T |          | U |
|                | 913-385 |          | T |          | U |
|                | 913-390 |          | T |          | U |
|                | 913-395 |          | T |          | U |
|                | 913-3MM |          | T |          | U |
|                | 913-400 |          | T |          | U |
|                | 913-405 |          | T |          | U |
|                | 913-410 |          | T |          | U |
|                | 913-415 |          | T |          | U |
|                | 913-420 |          | T |          | U |
|                | 913-425 |          | T |          | U |
|                | 913-430 |          | T |          | U |
|                | 913-435 |          | T |          | U |
|                | 913-437 |          | T |          | U |
|                | 913-440 |          | T |          | U |
|                | 913-445 |          | T |          | U |
|                | 913-450 |          | T |          | U |
|                | 913-455 |          | T |          | U |
|                | 913-460 |          | T |          | U |
|                | 913-465 |          | T |          | U |
|                | 913-470 |          | T |          | U |
|                | 913-475 |          | T |          | U |
|                | 913-480 |          | T |          | U |
|                | 913-485 |          | T |          | U |
|                | 913-490 |          | T |          | U |
|                | 913-495 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 913-4MM | Old Rev. | T | New Rev. | U |
|                | 913-500 |          | T |          | U |
|                | 913-505 |          | T |          | U |
|                | 913-510 |          | T |          | U |
|                | 913-515 |          | T |          | U |
|                | 913-520 |          | T |          | U |
|                | 913-525 |          | T |          | U |
|                | 913-530 |          | T |          | U |
|                | 913-535 |          | T |          | U |
|                | 913-540 |          | T |          | U |
|                | 913-545 |          | T |          | U |
|                | 913-550 |          | T |          | U |
|                | 913-555 |          | T |          | U |
|                | 913-560 |          | T |          | U |
|                | 913-565 |          | T |          | U |
|                | 913-570 |          | T |          | U |
|                | 913-575 |          | T |          | U |
|                | 913-580 |          | T |          | U |
|                | 913-585 |          | T |          | U |
|                | 913-590 |          | T |          | U |
|                | 913-595 |          | T |          | U |
|                | 913-5MM |          | T |          | U |
|                | 913-600 |          | T |          | U |
|                | 913-605 |          | T |          | U |
|                | 913-610 |          | T |          | U |
|                | 913-615 |          | T |          | U |
|                | 913-620 |          | T |          | U |
|                | 913-625 |          | T |          | U |
|                | 913-630 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 913-635 | Old Rev. | T | New Rev. | U |
|                | 913-640 |          | T |          | U |
|                | 913-645 |          | T |          | U |
|                | 913-650 |          | T |          | U |
|                | 913-655 |          | T |          | U |
|                | 913-660 |          | T |          | U |
|                | 913-665 |          | T |          | U |
|                | 913-670 |          | T |          | U |
|                | 913-675 |          | T |          | U |
|                | 913-680 |          | T |          | U |
|                | 913-685 |          | T |          | U |
|                | 913-690 |          | T |          | U |
|                | 913-695 |          | T |          | U |
|                | 913-6MM |          | T |          | U |
|                | 913-700 |          | T |          | U |
|                | 913-705 |          | T |          | U |
|                | 913-710 |          | T |          | U |
|                | 913-715 |          | T |          | U |
|                | 913-720 |          | T |          | U |
|                | 913-725 |          | T |          | U |
|                | 913-730 |          | T |          | U |
|                | 913-735 |          | T |          | U |
|                | 913-740 |          | T |          | U |
|                | 913-745 |          | T |          | U |
|                | 913-750 |          | T |          | U |
|                | 913-755 |          | T |          | U |
|                | 913-760 |          | T |          | U |
|                | 913-765 |          | T |          | U |
|                | 913-770 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 913-775 | Old Rev. | T | New Rev. | U |
|                | 913-780 |          | T |          | U |
|                | 913-785 |          | T |          | U |
|                | 913-790 |          | T |          | U |
|                | 913-795 |          | T |          | U |
|                | 913-7MM |          | T |          | U |
|                | 913-800 |          | T |          | U |
|                | 913-805 |          | T |          | U |
|                | 913-810 |          | T |          | U |
|                | 913-815 |          | T |          | U |
|                | 913-820 |          | T |          | U |
|                | 913-825 |          | T |          | U |
|                | 913-830 |          | T |          | U |
|                | 913-835 |          | T |          | U |
|                | 913-840 |          | T |          | U |
|                | 913-845 |          | T |          | U |
|                | 913-850 |          | T |          | U |
|                | 913-855 |          | T |          | U |
|                | 913-860 |          | T |          | U |
|                | 913-865 |          | T |          | U |
|                | 913-870 |          | T |          | U |
|                | 913-875 |          | T |          | U |
|                | 913-880 |          | T |          | U |
|                | 913-885 |          | T |          | U |
|                | 913-890 |          | T |          | U |
|                | 913-895 |          | T |          | U |
|                | 913-8MM |          | T |          | U |
|                | 913-900 |          | T |          | U |
|                | 913-905 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 913-910 | Old Rev. | T | New Rev. | U |
|                | 913-915 |          | T |          | U |
|                | 913-920 |          | T |          | U |
|                | 913-925 |          | T |          | U |
|                | 913-930 |          | T |          | U |
|                | 913-935 |          | T |          | U |
|                | 913-940 |          | T |          | U |
|                | 913-945 |          | T |          | U |
|                | 913-950 |          | T |          | U |
|                | 913-955 |          | T |          | U |
|                | 913-960 |          | T |          | U |
|                | 913-965 |          | T |          | U |
|                | 913-970 |          | T |          | U |
|                | 913-975 |          | T |          | U |
|                | 913-980 |          | T |          | U |
|                | 913-985 |          | T |          | U |
|                | 913-990 |          | T |          | U |
|                | 913-995 |          | T |          | U |
|                | 913-9MM |          | T |          | U |
|                | 938-020 |          | T |          | U |
|                | 938-030 |          | T |          | U |
|                | 938-035 |          | T |          | U |
|                | 938-040 |          | T |          | U |
|                | 938-045 |          | T |          | U |
|                | 938-050 |          | T |          | U |
|                | 938-055 |          | T |          | U |
|                | 938-060 |          | T |          | U |
|                | 938-065 |          | T |          | U |
|                | 938-070 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 938-075   | Old Rev. | T | New Rev. | U |
|                | 938-080   |          | T |          | U |
|                | 938-085   |          | T |          | U |
|                | 938-090   |          | T |          | U |
|                | 938-095   |          | T |          | U |
|                | 938-1.000 |          | T |          | U |
|                | 938-1.100 |          | T |          | U |
|                | 938-1.125 |          | T |          | U |
|                | 938-1.180 |          | T |          | U |
|                | 938-1.250 |          | T |          | U |
|                | 938-100   |          | T |          | U |
|                | 938-105   |          | T |          | U |
|                | 938-10MM  |          | T |          | U |
|                | 938-110   |          | T |          | U |
|                | 938-115   |          | T |          | U |
|                | 938-11MM  |          | T |          | U |
|                | 938-120   |          | T |          | U |
|                | 938-125   |          | T |          | U |
|                | 938-130   |          | T |          | U |
|                | 938-135   |          | T |          | U |
|                | 938-13MM  |          | T |          | U |
|                | 938-140   |          | T |          | U |
|                | 938-145   |          | T |          | U |
|                | 938-14MM  |          | T |          | U |
|                | 938-150   |          | T |          | U |
|                | 938-155   |          | T |          | U |
|                | 938-160   |          | T |          | U |
|                | 938-165   |          | T |          | U |
|                | 938-16MM  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |            |          |   |          |   |
|----------------|------------|----------|---|----------|---|
| Parts Affected | 938-170    | Old Rev. | T | New Rev. | U |
|                | 938-175    |          | T |          | U |
|                | 938-180    |          | T |          | U |
|                | 938-185    |          | T |          | U |
|                | 938-18MM   |          | T |          | U |
|                | 938-190    |          | T |          | U |
|                | 938-195    |          | T |          | U |
|                | 938-19MM   |          | T |          | U |
|                | 938-1MM    |          | T |          | U |
|                | 938-200    |          | T |          | U |
|                | 938-205    |          | T |          | U |
|                | 938-20MM   |          | T |          | U |
|                | 938-210    |          | T |          | U |
|                | 938-215    |          | T |          | U |
|                | 938-220    |          | T |          | U |
|                | 938-220 BK |          | T |          | U |
|                | 938-225    |          | T |          | U |
|                | 938-230    |          | T |          | U |
|                | 938-235    |          | T |          | U |
|                | 938-240    |          | T |          | U |
|                | 938-245    |          | T |          | U |
|                | 938-24MM   |          | T |          | U |
|                | 938-250    |          | T |          | U |
|                | 938-255    |          | T |          | U |
|                | 938-260    |          | T |          | U |
|                | 938-265    |          | T |          | U |
|                | 938-270    |          | T |          | U |
|                | 938-275    |          | T |          | U |
|                | 938-280    |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 938-285  | Old Rev. | T | New Rev. | U |
|                | 938-290  |          | T |          | U |
|                | 938-295  |          | T |          | U |
|                | 938-2MM  |          | T |          | U |
|                | 938-300  |          | T |          | U |
|                | 938-305  |          | T |          | U |
|                | 938-310  |          | T |          | U |
|                | 938-315  |          | T |          | U |
|                | 938-320  |          | T |          | U |
|                | 938-325  |          | T |          | U |
|                | 938-32MM |          | T |          | U |
|                | 938-330  |          | T |          | U |
|                | 938-335  |          | T |          | U |
|                | 938-340  |          | T |          | U |
|                | 938-345  |          | T |          | U |
|                | 938-350  |          | T |          | U |
|                | 938-355  |          | T |          | U |
|                | 938-360  |          | T |          | U |
|                | 938-365  |          | T |          | U |
|                | 938-370  |          | T |          | U |
|                | 938-375  |          | T |          | U |
|                | 938-380  |          | T |          | U |
|                | 938-385  |          | T |          | U |
|                | 938-390  |          | T |          | U |
|                | 938-395  |          | T |          | U |
|                | 938-3MM  |          | T |          | U |
|                | 938-400  |          | T |          | U |
|                | 938-405  |          | T |          | U |
|                | 938-410  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



# PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 938-415 | Old Rev. | T | New Rev. | U |
|                | 938-420 |          | T |          | U |
|                | 938-425 |          | T |          | U |
|                | 938-430 |          | T |          | U |
|                | 938-435 |          | T |          | U |
|                | 938-440 |          | T |          | U |
|                | 938-450 |          | T |          | U |
|                | 938-455 |          | T |          | U |
|                | 938-460 |          | T |          | U |
|                | 938-465 |          | T |          | U |
|                | 938-470 |          | T |          | U |
|                | 938-475 |          | T |          | U |
|                | 938-480 |          | T |          | U |
|                | 938-485 |          | T |          | U |
|                | 938-490 |          | T |          | U |
|                | 938-495 |          | T |          | U |
|                | 938-4MM |          | T |          | U |
|                | 938-500 |          | T |          | U |
|                | 938-505 |          | T |          | U |
|                | 938-510 |          | T |          | U |
|                | 938-515 |          | T |          | U |
|                | 938-520 |          | T |          | U |
|                | 938-525 |          | T |          | U |
|                | 938-530 |          | T |          | U |
|                | 938-535 |          | T |          | U |
|                | 938-540 |          | T |          | U |
|                | 938-545 |          | T |          | U |
|                | 938-550 |          | T |          | U |
|                | 938-555 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 938-560 | Old Rev. | T | New Rev. | U |
|                | 938-565 |          | T |          | U |
|                | 938-570 |          | T |          | U |
|                | 938-575 |          | T |          | U |
|                | 938-580 |          | T |          | U |
|                | 938-585 |          | T |          | U |
|                | 938-590 |          | T |          | U |
|                | 938-595 |          | T |          | U |
|                | 938-5MM |          | T |          | U |
|                | 938-600 |          | T |          | U |
|                | 938-605 |          | T |          | U |
|                | 938-610 |          | T |          | U |
|                | 938-615 |          | T |          | U |
|                | 938-620 |          | T |          | U |
|                | 938-625 |          | T |          | U |
|                | 938-630 |          | T |          | U |
|                | 938-635 |          | T |          | U |
|                | 938-640 |          | T |          | U |
|                | 938-645 |          | T |          | U |
|                | 938-650 |          | T |          | U |
|                | 938-655 |          | T |          | U |
|                | 938-660 |          | T |          | U |
|                | 938-665 |          | T |          | U |
|                | 938-670 |          | T |          | U |
|                | 938-675 |          | T |          | U |
|                | 938-680 |          | T |          | U |
|                | 938-685 |          | T |          | U |
|                | 938-690 |          | T |          | U |
|                | 938-695 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 938-6MM | Old Rev. | T | New Rev. | U |
|                | 938-700 |          | T |          | U |
|                | 938-705 |          | T |          | U |
|                | 938-710 |          | T |          | U |
|                | 938-715 |          | T |          | U |
|                | 938-720 |          | T |          | U |
|                | 938-725 |          | T |          | U |
|                | 938-730 |          | T |          | U |
|                | 938-735 |          | T |          | U |
|                | 938-740 |          | T |          | U |
|                | 938-745 |          | T |          | U |
|                | 938-750 |          | T |          | U |
|                | 938-755 |          | T |          | U |
|                | 938-760 |          | T |          | U |
|                | 938-765 |          | T |          | U |
|                | 938-770 |          | T |          | U |
|                | 938-775 |          | T |          | U |
|                | 938-780 |          | T |          | U |
|                | 938-785 |          | T |          | U |
|                | 938-790 |          | T |          | U |
|                | 938-795 |          | T |          | U |
|                | 938-7MM |          | T |          | U |
|                | 938-800 |          | T |          | U |
|                | 938-805 |          | T |          | U |
|                | 938-810 |          | T |          | U |
|                | 938-815 |          | T |          | U |
|                | 938-820 |          | T |          | U |
|                | 938-825 |          | T |          | U |
|                | 938-830 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 938-835 | Old Rev. | T | New Rev. | U |
|                | 938-840 |          | T |          | U |
|                | 938-845 |          | T |          | U |
|                | 938-850 |          | T |          | U |
|                | 938-855 |          | T |          | U |
|                | 938-860 |          | T |          | U |
|                | 938-865 |          | T |          | U |
|                | 938-870 |          | T |          | U |
|                | 938-875 |          | T |          | U |
|                | 938-880 |          | T |          | U |
|                | 938-885 |          | T |          | U |
|                | 938-890 |          | T |          | U |
|                | 938-895 |          | T |          | U |
|                | 938-8MM |          | T |          | U |
|                | 938-900 |          | T |          | U |
|                | 938-905 |          | T |          | U |
|                | 938-910 |          | T |          | U |
|                | 938-915 |          | T |          | U |
|                | 938-920 |          | T |          | U |
|                | 938-925 |          | T |          | U |
|                | 938-930 |          | T |          | U |
|                | 938-935 |          | T |          | U |
|                | 938-940 |          | T |          | U |
|                | 938-945 |          | T |          | U |
|                | 938-950 |          | T |          | U |
|                | 938-955 |          | T |          | U |
|                | 938-960 |          | T |          | U |
|                | 938-965 |          | T |          | U |
|                | 938-970 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 938-975   | Old Rev. | T | New Rev. | U |
|                | 938-980   |          | T |          | U |
|                | 938-985   |          | T |          | U |
|                | 938-990   |          | T |          | U |
|                | 938-995   |          | T |          | U |
|                | 938-9MM   |          | T |          | U |
|                | 940-030   |          | T |          | U |
|                | 940-035   |          | T |          | U |
|                | 940-040   |          | T |          | U |
|                | 940-045   |          | T |          | U |
|                | 940-050   |          | T |          | U |
|                | 940-055   |          | T |          | U |
|                | 940-060   |          | T |          | U |
|                | 940-065   |          | T |          | U |
|                | 940-070   |          | T |          | U |
|                | 940-075   |          | T |          | U |
|                | 940-080   |          | T |          | U |
|                | 940-085   |          | T |          | U |
|                | 940-090   |          | T |          | U |
|                | 940-095   |          | T |          | U |
|                | 940-1.000 |          | T |          | U |
|                | 940-1.005 |          | T |          | U |
|                | 940-1.010 |          | T |          | U |
|                | 940-1.015 |          | T |          | U |
|                | 940-1.020 |          | T |          | U |
|                | 940-1.025 |          | T |          | U |
|                | 940-1.030 |          | T |          | U |
|                | 940-1.035 |          | T |          | U |
|                | 940-1.040 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 940-1.045 | Old Rev. | T | New Rev. | U |
|                | 940-1.050 |          | T |          | U |
|                | 940-1.055 |          | T |          | U |
|                | 940-1.060 |          | T |          | U |
|                | 940-1.065 |          | T |          | U |
|                | 940-1.070 |          | T |          | U |
|                | 940-1.075 |          | T |          | U |
|                | 940-1.080 |          | T |          | U |
|                | 940-1.085 |          | T |          | U |
|                | 940-1.090 |          | T |          | U |
|                | 940-1.095 |          | T |          | U |
|                | 940-1.100 |          | T |          | U |
|                | 940-1.105 |          | T |          | U |
|                | 940-1.110 |          | T |          | U |
|                | 940-1.115 |          | T |          | U |
|                | 940-1.120 |          | T |          | U |
|                | 940-1.125 |          | T |          | U |
|                | 940-1.130 |          | T |          | U |
|                | 940-1.135 |          | T |          | U |
|                | 940-1.140 |          | T |          | U |
|                | 940-1.145 |          | T |          | U |
|                | 940-1.150 |          | T |          | U |
|                | 940-1.155 |          | T |          | U |
|                | 940-1.160 |          | T |          | U |
|                | 940-1.165 |          | T |          | U |
|                | 940-1.170 |          | T |          | U |
|                | 940-1.175 |          | T |          | U |
|                | 940-1.180 |          | T |          | U |
|                | 940-1.185 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |           |          |   |          |   |
|----------------|-----------|----------|---|----------|---|
| Parts Affected | 940-1.190 | Old Rev. | T | New Rev. | U |
|                | 940-1.195 |          | T |          | U |
|                | 940-1.200 |          | T |          | U |
|                | 940-1.205 |          | T |          | U |
|                | 940-1.210 |          | T |          | U |
|                | 940-1.215 |          | T |          | U |
|                | 940-1.220 |          | T |          | U |
|                | 940-1.225 |          | T |          | U |
|                | 940-1.230 |          | T |          | U |
|                | 940-1.235 |          | T |          | U |
|                | 940-1.240 |          | T |          | U |
|                | 940-1.245 |          | T |          | U |
|                | 940-1.250 |          | T |          | U |
|                | 940-100   |          | T |          | U |
|                | 940-105   |          | T |          | U |
|                | 940-10MM  |          | T |          | U |
|                | 940-110   |          | T |          | U |
|                | 940-115   |          | T |          | U |
|                | 940-11MM  |          | T |          | U |
|                | 940-120   |          | T |          | U |
|                | 940-125   |          | T |          | U |
|                | 940-12MM  |          | T |          | U |
|                | 940-130   |          | T |          | U |
|                | 940-135   |          | T |          | U |
|                | 940-13MM  |          | T |          | U |
|                | 940-140   |          | T |          | U |
|                | 940-145   |          | T |          | U |
|                | 940-150   |          | T |          | U |
|                | 940-155   |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 940-15MM | Old Rev. | T | New Rev. | U |
|                | 940-160  |          | T |          | U |
|                | 940-165  |          | T |          | U |
|                | 940-170  |          | T |          | U |
|                | 940-175  |          | T |          | U |
|                | 940-180  |          | T |          | U |
|                | 940-185  |          | T |          | U |
|                | 940-18MM |          | T |          | U |
|                | 940-190  |          | T |          | U |
|                | 940-195  |          | T |          | U |
|                | 940-19MM |          | T |          | U |
|                | 940-1MM  |          | T |          | U |
|                | 940-200  |          | T |          | U |
|                | 940-205  |          | T |          | U |
|                | 940-20MM |          | T |          | U |
|                | 940-210  |          | T |          | U |
|                | 940-215  |          | T |          | U |
|                | 940-21MM |          | T |          | U |
|                | 940-220  |          | T |          | U |
|                | 940-225  |          | T |          | U |
|                | 940-22MM |          | T |          | U |
|                | 940-230  |          | T |          | U |
|                | 940-235  |          | T |          | U |
|                | 940-23MM |          | T |          | U |
|                | 940-240  |          | T |          | U |
|                | 940-245  |          | T |          | U |
|                | 940-24MM |          | T |          | U |
|                | 940-250  |          | T |          | U |
|                | 940-255  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |          |          |   |          |   |
|----------------|----------|----------|---|----------|---|
| Parts Affected | 940-25MM | Old Rev. | T | New Rev. | U |
|                | 940-260  |          | T |          | U |
|                | 940-265  |          | T |          | U |
|                | 940-270  |          | T |          | U |
|                | 940-275  |          | T |          | U |
|                | 940-280  |          | T |          | U |
|                | 940-285  |          | T |          | U |
|                | 940-290  |          | T |          | U |
|                | 940-295  |          | T |          | U |
|                | 940-2MM  |          | T |          | U |
|                | 940-300  |          | T |          | U |
|                | 940-305  |          | T |          | U |
|                | 940-310  |          | T |          | U |
|                | 940-315  |          | T |          | U |
|                | 940-320  |          | T |          | U |
|                | 940-325  |          | T |          | U |
|                | 940-330  |          | T |          | U |
|                | 940-335  |          | T |          | U |
|                | 940-340  |          | T |          | U |
|                | 940-345  |          | T |          | U |
|                | 940-350  |          | T |          | U |
|                | 940-355  |          | T |          | U |
|                | 940-360  |          | T |          | U |
|                | 940-365  |          | T |          | U |
|                | 940-370  |          | T |          | U |
|                | 940-375  |          | T |          | U |
|                | 940-380  |          | T |          | U |
|                | 940-385  |          | T |          | U |
|                | 940-390  |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 940-395 | Old Rev. | T | New Rev. | U |
|                | 940-3MM |          | T |          | U |
|                | 940-400 |          | T |          | U |
|                | 940-405 |          | T |          | U |
|                | 940-410 |          | T |          | U |
|                | 940-415 |          | T |          | U |
|                | 940-420 |          | T |          | U |
|                | 940-425 |          | T |          | U |
|                | 940-430 |          | T |          | U |
|                | 940-435 |          | T |          | U |
|                | 940-440 |          | T |          | U |
|                | 940-445 |          | T |          | U |
|                | 940-450 |          | T |          | U |
|                | 940-455 |          | T |          | U |
|                | 940-460 |          | T |          | U |
|                | 940-465 |          | T |          | U |
|                | 940-470 |          | T |          | U |
|                | 940-475 |          | T |          | U |
|                | 940-480 |          | T |          | U |
|                | 940-485 |          | T |          | U |
|                | 940-490 |          | T |          | U |
|                | 940-495 |          | T |          | U |
|                | 940-4MM |          | T |          | U |
|                | 940-500 |          | T |          | U |
|                | 940-505 |          | T |          | U |
|                | 940-510 |          | T |          | U |
|                | 940-515 |          | T |          | U |
|                | 940-520 |          | T |          | U |
|                | 940-525 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 940-530 | Old Rev. | T | New Rev. | U |
|                | 940-535 |          | T |          | U |
|                | 940-540 |          | T |          | U |
|                | 940-545 |          | T |          | U |
|                | 940-550 |          | T |          | U |
|                | 940-555 |          | T |          | U |
|                | 940-560 |          | T |          | U |
|                | 940-565 |          | T |          | U |
|                | 940-570 |          | T |          | U |
|                | 940-575 |          | T |          | U |
|                | 940-580 |          | T |          | U |
|                | 940-585 |          | T |          | U |
|                | 940-590 |          | T |          | U |
|                | 940-595 |          | T |          | U |
|                | 940-5MM |          | T |          | U |
|                | 940-600 |          | T |          | U |
|                | 940-605 |          | T |          | U |
|                | 940-610 |          | T |          | U |
|                | 940-615 |          | T |          | U |
|                | 940-620 |          | T |          | U |
|                | 940-625 |          | T |          | U |
|                | 940-630 |          | T |          | U |
|                | 940-635 |          | T |          | U |
|                | 940-640 |          | T |          | U |
|                | 940-645 |          | T |          | U |
|                | 940-650 |          | T |          | U |
|                | 940-655 |          | T |          | U |
|                | 940-660 |          | T |          | U |
|                | 940-665 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 940-670 | Old Rev. | T | New Rev. | U |
|                | 940-675 |          | T |          | U |
|                | 940-680 |          | T |          | U |
|                | 940-685 |          | T |          | U |
|                | 940-690 |          | T |          | U |
|                | 940-695 |          | T |          | U |
|                | 940-6MM |          | T |          | U |
|                | 940-700 |          | T |          | U |
|                | 940-705 |          | T |          | U |
|                | 940-710 |          | T |          | U |
|                | 940-715 |          | T |          | U |
|                | 940-720 |          | T |          | U |
|                | 940-725 |          | T |          | U |
|                | 940-730 |          | T |          | U |
|                | 940-735 |          | T |          | U |
|                | 940-740 |          | T |          | U |
|                | 940-745 |          | T |          | U |
|                | 940-750 |          | T |          | U |
|                | 940-755 |          | T |          | U |
|                | 940-760 |          | T |          | U |
|                | 940-765 |          | T |          | U |
|                | 940-770 |          | T |          | U |
|                | 940-775 |          | T |          | U |
|                | 940-780 |          | T |          | U |
|                | 940-785 |          | T |          | U |
|                | 940-790 |          | T |          | U |
|                | 940-795 |          | T |          | U |
|                | 940-7MM |          | T |          | U |
|                | 940-800 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 940-805 | Old Rev. | T | New Rev. | U |
|                | 940-810 |          | T |          | U |
|                | 940-815 |          | T |          | U |
|                | 940-820 |          | T |          | U |
|                | 940-825 |          | T |          | U |
|                | 940-830 |          | T |          | U |
|                | 940-835 |          | T |          | U |
|                | 940-840 |          | T |          | U |
|                | 940-845 |          | T |          | U |
|                | 940-850 |          | T |          | U |
|                | 940-855 |          | T |          | U |
|                | 940-860 |          | T |          | U |
|                | 940-865 |          | T |          | U |
|                | 940-870 |          | T |          | U |
|                | 940-875 |          | T |          | U |
|                | 940-880 |          | T |          | U |
|                | 940-885 |          | T |          | U |
|                | 940-890 |          | T |          | U |
|                | 940-895 |          | T |          | U |
|                | 940-8MM |          | T |          | U |
|                | 940-900 |          | T |          | U |
|                | 940-905 |          | T |          | U |
|                | 940-910 |          | T |          | U |
|                | 940-915 |          | T |          | U |
|                | 940-920 |          | T |          | U |
|                | 940-925 |          | T |          | U |
|                | 940-930 |          | T |          | U |
|                | 940-935 |          | T |          | U |
|                | 940-940 |          | T |          | U |

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122



## PRODUCT CHANGE NOTIFICATION

PCN No: PCN-1092

Issue Date: 8/21/2025

|                |         |          |   |          |   |
|----------------|---------|----------|---|----------|---|
| Parts Affected | 940-945 | Old Rev. | T | New Rev. | U |
|                | 940-950 |          | T |          | U |
|                | 940-955 |          | T |          | U |
|                | 940-960 |          | T |          | U |
|                | 940-965 |          | T |          | U |
|                | 940-970 |          | T |          | U |
|                | 940-975 |          | T |          | U |
|                | 940-980 |          | T |          | U |
|                | 940-985 |          | T |          | U |
|                | 940-990 |          | T |          | U |
|                | 940-995 |          | T |          | U |
|                | 940-9MM |          | T |          | U |

### Change Will Affect:

This change will result in an update to the product specifications on the drawing.

### Description of Change:

The angle tolerance specification is being updated from  $\pm 0.5^\circ$  to  $\pm 1.5^\circ$ . This change is being implemented to align with current manufacturing capabilities and will now serve as a reference specification.

**Effective Date of Change:** August 21, 2025

**Reason for Change:** To align with current manufacturing capabilities.

These changes have been reviewed and approved by Bivar management per Bivar Procedure: Engineering Change Order and Part Change Notification, SOP-040, SOP-ENG-045

Please contact Bivar Inc. at [www.bivar.com/contact](http://www.bivar.com/contact) or speak to a Bivar representative for any questions or support requirements within 30 days of issue date.

BV00-Q465 REV 92122