

Product Change Notification

520 Park East Blvd., New Albany, IN 47150 U.S.A (812)-944-6733 / 1-800-SAMTEC9

1. ECR #: 218869 Notification #: 658

2. Date of Announcement: November 18, 2022

3. Series:

• UMPS - UMPS ASSEMBLY

4. Part #'s Affected


• UMPS-XX-XX.X-XX-V-X-XR


5. Description of Change:

Change the outer void of side rib design and add void to right Weld tab hole.

6. Method of Identifying Change

Visual inspection, see picture for the body changes highlighted in blue color.





New Part

7. Reason for Change:

Change made to improve body knit line.

8. Impact of Change on Form, Fit, or Function:

- Form this is a rolling change and there is some opportunity for mixed inventory on a limited basis.
- 9. Projected Implementation Date: December 18, 2022

Disclaimer

Please review the change notification details listed above for specific information regarding the nature and timing of the change. While Samtec has taken precautions to ensure this change is not detrimental to your application, each application can be unique and therefore customers should consider the effect of the change on their specific application.

Samtec has taken efforts to ensure that all users of this product who have requested change notifications have been informed. However, you should assume that this is the only notification that will be sent and you, as the recipient, must determine how to communicate this information to your organization(s) and customer(s) as appropriate. If you wish to opt out of receiving Samtec Product Change Notification emails, please contact CustomerECN@samtec.com. Due to technical progress, specifications are subject to change without notification and it is recommended to provide an alternative contact when opting out.

Please contact Samtec at <u>CustomerECN@samtec.com</u> for any questions related to this change.