

Product Change Notification (PCN)

PCN Number | 508341

Date Issued

March 27, 2020

Reason for Change

Capacity change or tool replacement

Change Type Description

This letter is to inform you that another set of tooling is being added to meet the current and future demands of this product. There will be no changes in the fit, form or function from the additional tooling when compared to the current tooling.

Assessment of Change

Product will be fully qualified before it is shipped. Qualification reports will be available after below listed date

Internal Molex Qualification Date

August 01, 2020

Sample Availability Date (Changed Part)

August 01, 2020

Planned Implementation Date


September 25, 2020

Method of Identifying Change

Product made after planned implementation date can contain the change

Before Change

.093 Diameter Crimp terminals



molex

After Change

Overview New Tooling

- Molex Lincoln Kingbird is building new .093 diameter crimp terminal dies
- Tooling is being added to meet current and future demands for product
- Product Impact
 - No Impact to Fit, Form or Function
- Part Number Impact
 - See attached impacted parts list
- Qualification Reports and samples available upon request after the date shown above

molex



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "PCN Notification:508341" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

| PCN # | Molex Part # |
|--------|--------------|
| 508341 | 2091102 |
| 508341 | 2091104 |
| 508341 | 2091115 |
| 508341 | 2091117 |
| 508341 | 2091119 |
| 508341 | 2091205 |
| 508341 | 2092101 |
| 508341 | 2092103 |
| 508341 | 2092116 |
| 508341 | 2092118 |
| 508341 | 2092166 |
| 508341 | 2095100 |
| 508341 | 2096100 |
| 508341 | 2096102 |
| 508341 | 2096122 |