

www.trinamic.com

February 19, 2020

+49 (0) 40 514 806 0 +49 (0) 40 514 806 60

tmc_info@trinamic.com www.trinamic.com

TEL FAX

MAIL WEB

Dear Valued TRINAMIC Customer,

this is to inform you that a firmware change has been released for the modules listed in table below.

TMCM-1640

New batches of modules will be delivered together with new firmware release V2.10. Modules already shipped can be updated to this new release using the provided firmware update feature of the TMCL-IDE. Prior releases are still available on the corresponding product pages on www.trinamic.com.

Firmware Changes

The following firmware changes have been applied:

Axis parameter 255 (enable driver) added.

This improvement is classified as a minor change (application dependent). Verification of changes in application is required.

Products Affected

Article Name	Affected Article Numbers
TMCM-1640	11-0043
PD42-4-1640	30-0321

Timing

Effective date February 19, 2020

TRINAMIC Motion Control GmbH & Co. KG

MANAGEMENT TEAM	DiplIng. Michael Randt DiplInform. Bernhard Dwersteg Dr. rer. nat. Lars Larsson Dr. Tonio Barlage	ADDRESS	Waterloohain 5 22769 Hamburg Germany
REGISTRATION COURT	Hamburg HRA 100972		
VAT ID NR	DE 814127182		
COMPLEMENTARY	TRINAMIC Verwaltungsgesellschaft mbH (Registration Court Hamburg HRB 91746)		