

Complies with IEC 601010 1KV CAT III

VARIANTS

FCR19507B - TPR7 TEST PROBE BLACK CLIFF FCR19507G - TPR7 TEST PROBE GREEN CLIFF FCR19507L - TPR7 TEST PROBE BLUE CLIFF FCR19507N - TPR7 TEST PROBE BROWN CLIFF FCR19507R - TPR7 TEST PROBE RED CLIFF

FCR19507RB - TPR7 TEST PROBE PAIR RED+BLACK

© CLIFF 10/2022 ISS.1

For further information, contact sales@cliffuk.co.uk

Cliff Electronic Components Limited,

76 Holmethorpe Avenue, Holmethorpe Ind. Estate, Redhill, Surrey RH1 2PF U.K.

Tel: +44 (0)1737 771375 Fax: +44 (0)1737 766012









Key Features / Product Overview

- Compatible with universal standard 4 mm shrouded plugs
- Conforms to EN61010-031
- IEC Measurement Category III CAT III equipment is designed for measurements performed in the building installation.

Technical Specifications

- Test Probe 1kV AC/DC 10A CAT III (Double Insulated)
- Designed to comply with EN61010-031
- Environmental ratings: -10 °C to 40 °C (14 °F to 104 °F), altitude: 2000 m (6,562 ft)

Warnings	and	Descri	ption (of N	Marking	35

Double or Reinforced Insulation

Caution <u>(1</u>

UK Conformity Assessed

Conformité Européenne



To prevent electric shock or personal injury:

- The MEASUREMENT CATEGORY of a combination of a probe assembly and an accessory is the LOWER of the MEASUREMENT CATEGORIES of the probe assembly AND of the accessory.
- It is the end user's responsibility to ensure this device is used in a safe manner to ensure no injury is caused to operators. Failure to follow these instructions or use this equipment in a manner not specified by the manufacturer, could impair the safety of the equipment.
- · Protect the leads and accessories from damage, e.g., cuts and abrasions. Keep clean and dry.
- Before use check the probe assembly for damage If in doubt DO NOT USE.
- Equipment, test leads and accessories should be inspected and tested regularly during their life to ensure the integrity of the insulation and that their continuity has not been compromised. If in doubt, contact the manufacturer for advice.
- DO NOT change accessories while connected to live or potentially live circuits
- Check the protection features, fusing and safety ratings of the test meter itself are compatible before using with these test leads.
- Clean with a soft towel moistened with water and mild detergent. (DO NOT IMMERSE in liquid).
- The probe assembly does not contain any serviceable parts. If in doubt please contact the manufacturer, DO NOT attempt to service the probe assembly.
- · DO NOT USE in wet or damp locations.
- DO ENSURE that the test leads are firmly connected to the instrument and other accessories.
- · DO NOT USE above the maximum ratings.
- DO NOT USE the probe assembly if the insulation around the probe tip is damaged or worn.

For further information, contact sales@cliffuk.co.uk

76 Holmethorpe Avenue, Holmethorpe Ind. Estate, Redhill, Surrey RH1 2PF U.K.

Tel: +44 (0)1737 771375 Fax: +44 (0)1737 766012

