

# **Product Change Notification**

 Date Issued :
 July 03, 2025
 PCN Number :
 516856

 Reason for Change :
 Manufacturing Process Change (Molex)

 Description of Change :
 This notification is to inform about manufacturing process change for the part/s listed in this notice is changing.

**Assessment of Change**: Reliability Test Report/s

Planned Implementation Date : January 30, 2026

Customer Sample Availability Date: September 01, 2025

Last date to request Samples by Customer: September 01, 2025

Please note if Samples are not requested as per Customer Samples Request date, it may take additional 4-6 weeks to arrange Samples.

Traceability Code Markings / Date : Date code

**Before Picture** 

## Overview

## PCN for Hi coat process





Hi coat process device Photo is used as representation of product only and may not be exact to product you received

After Picture

### Overview

- This PCN is for removal of Hi-coat on listed 505448 \*\*71, 505433 \*\*71, 204530 \*\*31, 505568 \*\*70 series. It will make the series PFAS Free to meet foreseen industry requirement from some customers.
- Product Impact
  - There is no impact to fit, form, appearance or functional specification.
     Verified listed products do not have flux wicking issues without Hi-coat.
- Part Number Impact
  - Refer to part number listed
- PCN will be implemented once all required qualification/ validation has been completed and all necessary approvals have been obtained



You may address inquires regarding this PCN by clicking on the below link mailto:pcn\_coordinator@molex.com?subject=PCN\_Notification:516856 or contact your Local Sales Engineer.

Note: While responding, please retain " PCN Notification: PCN Notification: 516856" in the e-mail Subject line for faster response.

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL (800) 786-6539 www.molex.com

#### PCN No Part List

- 516856 2045300231
- 516856 2045300331
- 516856 2045300431
- 516856 2045300831
- 516856 5054330871
- 516856 5054331071
- 516856 <u>5054331271</u>
- 516856 5054331471
- 516856 5054331671
- 516856 5054331871
- 516856 5054332071
- 516856 5054332271
- 919999 <u>900 (9022) 1</u>
- 516856 <u>5054332471</u>
- 516856 5054332671
- 516856 5054332871
- 516856 <u>5054333071</u>
- 516856 <u>5054333271</u>
- 516856 5054333471
- 516856 5054333671
- 516856 5054334071
- 516856 5054334271
- 516856 5054480871
- 516856 5054481071
- 516856 <u>5054481271</u>
- 310030 <u>3034401271</u>
- 516856 5054481471
- 516856 <u>5054481671</u>
- 516856 <u>5054481871</u>
- 516856 <u>5054482071</u>
- 516856 <u>5054482271</u>
- 516856 <u>5054482471</u>
- 516856 <u>5054482671</u>
- 516856 <u>5054482871</u>
- 516856 <u>5054483071</u>
- 516856 5054483271
- 516856 <u>5054483471</u>
- 516856 <u>5054483671</u>
- 516856 5054483871
- 516856 <u>5054484071</u>
- 516856 <u>5054484271</u>
- 516856 <u>5055680270</u>
- 516856 5055680370
- 516856 <u>5055680470</u>
- 516856 5055680570
- 516856 5055680670
- 516856 5055680770

516856 5055680870

516856 5055680970

516856 5055681070

516856 5055681170

516856 5055681270

516856 5055681370

516856 <u>5055681470</u>

516856 <u>5055681570</u>

516856 <u>5055681670</u>