

## **Global Change Notification (GCN)**

Product Family	HD - Industrial Micro D	10651819	
		GCN Number	
Series	Various	August 26, 2014	
		Date Issued	
Reason For Change	Product Component Change		
Change Description	This letter is to inform you of a change to the proprietary, formulary blend on the boots for the Commercial Micro D Connector Kit. Part numbers affected are: 830100071, 830100072, and 830100017, in kits 83421-9014, 83422-9014, and 83424-9014. The reason for this change is that a component material item is no longer available for use. There is no change to the form, fit, or function of the product, and the change applies only to the boots in the Commercial Micro D kits. The change does not apply to the Commercial Micro D cable assemblies.		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.		
Reason For Short Notice Exception	Force Majeure		
Assessment Of Change (How Product Will Be Qualified & Validated)	Qualification from First Article inspection		
Internal Molex Qualification Date (Planned Date Information Available)	August 15, 2014		
Sample Availability Date (Changed Part)			
Date of Implementation	August 31, 2014		
Method of Identifying Change	Label Date		
Recommended Replacement Parts	NA		
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com